



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007564/Utf3n2	Date: 29/07/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SCN 4000P	Veh. Inspected	SGX 3433E	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010856/KY	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	13/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	SUZUKI SX4 (A)	c.c	1586	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	JSAGYA21S00109463	Colour	WHITE	
Odometer	238366 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	KUMHO	6 mm	
L/H Rear Tyre	215/55 R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2021	Inspection Date	13/07/2021	
Survey held at	ZERO GRAVITY 2 KAKI BUKIT AVE 2 #01-25 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	