

ASS. REQ. BY:

Stere

CS/AIG 21007568 /EVF3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

SIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Cum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMH 5748Y

Yr Regn:

28/1/19

Type:

M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

KIA Cerato

c.c. 1591

Colour:

Grey

A/C:

Insured / Std / NI / N

Sp. Reading

23457

T/Radio:

Insured / Std / NI / PI

Eng/No:

C/No:

KNAIF 3416.MK 5.924748

Gen. Cond:

Good / Fair / Poor / Burnt

Steering: In order / Jammed / Locked / Burnt or

Brakes: In order / Jammed / Locked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nfera

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

L/Bal:

4

mm

L/Bal:

4

mm

D.O.A.

19/7/21

D.O.I.

13/7/21

Survey held at

Cock &amp; Conlay

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

M/V-72K

Date/Time, File, Pass to?



: Prel. Report



: Final Report

Date/Time, File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$

\$ + RS. 81



: Interview (\$

Provision



: Tech. Inve (\$

Others




: Weekend (\$

TOTAL

Approved by:

Date/Time/Signature



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

**ESTIMATE**

GST Reg No : MR-8500111-X


| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name /ONG JIAN DE<br>Reg No/Reg Date SMH5748Y / 28/01/201<br>Date In/Mileage / 23457<br>Chassis No KNAF3416MK5024748<br>Engine No G4FGJH713608<br>Make/Model KIA/CERATO 1.6 A EX G333<br>Colour/Trim KLG STEEL GREY / WK SATURN BLACK |

| Account No  | Terms  | Date/Time Printed | CSE | Operator          | WIP No     |       |              |
|---|--------|-------------------|-----|-------------------|------------|-------|--------------|
| LAX00000  | Credit | 12/07/2021/ 19:21 | BLE | 261 / Edwin Caina | 35995      |       |              |
| Description of Goods / Services                                     |        |                   |     | Qty               | Unit Price | Disc% | Amount       |
| E PNT88000  |        |                   |     | 1-5 X 400         |            |       | 600 2000.00  |
| RENEW (FR PORTION) FR BUMPER , BONNET & FR SUPPORT                  |        |                   |     |                   |            |       |              |
| REPAIR LHF FENDER & RHF FENDER                                      |        |                   |     |                   |            |       |              |
| E PNT88000  |        |                   |     | 4.5 X 400         |            |       | 1800 4000.00 |
| RENEW RR BUMPER , RR END PNL & BOOTLID                              |        |                   |     |                   |            |       |              |
| REPAIR RR FLR PNL , LHR FENDER , RHR FENDER , RR CHASSIS & LHR DOOR |        |                   |     |                   |            |       |              |
| E PNT98000  |        |                   |     | 6 X 350           |            |       | 2100 4200.00 |
| RESPRAY FRT BUMPER , BONNET , LHF FENDER , RHF FENDER ,             |        |                   |     |                   |            |       |              |
| RR BUMPER , RR END PNL , RR FLR PNL , LHR FENDER , RHR FENDER ,     |        |                   |     |                   |            |       |              |
| RR CHASSIS , LHF DOOR , RHF DOOR & LHR DOOR                         |        |                   |     |                   |            |       |              |
| E PNT88000  |        |                   |     |                   |            |       | 100.00       |
| REMOVE & REFIT AC COND & RADIATOR                                   |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | 80.00        |
| TOP UP AC GAS   |        |                   |     |                   |            |       |              |
| E PNT88000  |        |                   |     |                   |            |       | 120.00       |
| REMOVE & REFIT BOOTLID COMPONENT                                    |        |                   |     |                   |            |       |              |
| E PNT88000  |        |                   |     | (photo)           |            |       | 120.00       |
| REMOVE & REFIT RR FLR BOARD , TRIM , CARPET & SEAT                  |        |                   |     |                   |            |       |              |
| A 54900099  |        |                   |     |                   |            |       | 30.00        |
| CHECK WIRING ELECTRICAL SYSTEM                                      |        |                   |     |                   |            |       |              |
| A 10028901  |        |                   |     |                   |            |       | 120.00       |
| TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM          |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | 50.00        |
| SUPPLY FR NUMBER PLATE WITH CASING BR                               |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | X 50.00      |
| SUPPLY RR NUMBER PLATE WITH CASING                                  |        |                   |     |                   |            |       |              |
| E PNT88000  |        |                   |     |                   |            |       | 80.00        |
| TO RENEW REVERSE SENSOR   |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | 220.00       |
| SUPPLY REVERSE SENSOR BR  |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | 40 80.00     |
| APPLY ANTI CORROSION ON AFFECTED AREAS                              |        |                   |     |                   |            |       |              |
| M SUNDRY  |        |                   |     |                   |            |       | 40 80.00     |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K


| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name /ONG JIAN DE<br>Reg No/Reg Date SMH5748Y / 28/01/201<br>Date In/Mileage / 23457<br>Chassis No KNAF3416MK5024748<br>Engine No G4FGJH713608<br>Make/Model KIA/CERATO 1.6 A EX G333<br>Colour/Trim KLG STEEL GREY / WK SATURN BLACK |

| Account No                      | Terms                          | Date/Time Printed | CSE | Operator          | WIP No  |            |         |        |
|---------------------------------|--------------------------------|-------------------|-----|-------------------|---------|------------|---------|--------|
| LAX00000                        | Credit                         | 12/07/2021/ 19:21 | BLE | 261 / Edwin Caina | 35995   |            |         |        |
| Description of Goods / Services |                                |                   |     |                   | Qty     | Unit Price | Disc%   | Amount |
| SUPPLY BODY PNL SEALANT         |                                |                   |     |                   |         |            |         | 40.00  |
| M SUNDRY                        |                                |                   |     |                   |         |            |         |        |
| SUPPLY C&C BADGE                |                                |                   |     |                   |         |            |         | 30.00  |
| M SUNDRY                        |                                |                   |     |                   |         |            |         |        |
| Sundries                        |                                |                   |     |                   |         |            |         |        |
| M                               | COVER-FR BUMPER                | BR                | CRA | 1.00              | 633.00  | 20.00      | 506.40  |        |
| M                               | GRILLE-FRONT BUMPER            | CUT               |     | 1.00              | 262.00  | 20.00      | 209.60  |        |
| M                               | GRILLE ASSY-RADIATOR           | CRA               |     | 1.00              | 328.00  | 20.00      | 262.40  |        |
| M                               | ABSORBER-FRONT BUMPER ENERGY   |                   |     | 1.00              | 84.00   | 20.00      | 67.20   |        |
| M                               | STIFFNER-FR BPR LWR            |                   |     | 1.00              | 114.00  | 20.00      | 91.20   |        |
| M                               | BRACKET-FR BUMPER UPR SIDE MTG |                   |     | 1.00              | 22.00   | 20.00      | 17.60   |        |
| M                               | BRACKET-FR BUMPER UPR SIDE MTG |                   |     | 1.00              | 22.00   | 20.00      | 17.60   |        |
| M                               | PANEL ASSY-HOOD                | DD                |     | 1.00              | 1502.00 | 20.00      | 1201.60 |        |
| M                               | BEAM COMPLETE-FR BUMPER        |                   |     | 1.00              | 497.00  | 20.00      | 397.60  |        |
| M                               | CARRIER ASSY-FRONT END MODULE  |                   |     | 1.00              | 675.00  | 20.00      | 540.00  |        |
| M                               | ORNAMENT-KIA NO.115            | nec               |     | 1.00              | 32.00   | 20.00      | 25.60   |        |
| M                               | LOGO ASSY-KIA SUB              | nec               |     | 1.00              | 32.00   | 20.00      | 25.60   |        |
| M                               | EMBLEM-CERATO                  | nec               |     | 1.00              | 28.00   | 20.00      | 22.40   |        |
| M                               | COVER-RR BUMPER                | BR                |     | 1.00              | 651.00  | 20.00      | 520.80  |        |
| M                               | COVER-RR BUMPER LWR            | BR                |     | 1.00              | 241.00  | 20.00      | 192.80  |        |
| M                               | COVER-RR BUMPER UNDER, LH      |                   |     | 1.00              | 33.00   | 20.00      | 26.40   |        |
| M                               | COVER-RR BUMPER FOG LAMP, LH   |                   |     | 1.00              | 19.00   | 20.00      | 15.20   |        |
| M                               | COVER-RR BUMPER FOG LAMP, RH   |                   |     | 1.00              | 19.00   | 20.00      | 15.20   |        |
| M                               | LAMP ASSY-SIDE T/SIGNAL, LH    |                   |     | 1.00              | 181.00  | 20.00      | 144.80  |        |
| M                               | LAMP ASSY-SIDE T/SIGNAL, RH    |                   |     | 1.00              | 181.00  | 20.00      | 144.80  |        |
| M                               | EXTN WIRING ASSY-BWS           |                   |     | 1.00              | 207.00  | 20.00      | 165.60  |        |
| M                               | BEAM-RR BUMPER                 | BR                |     | 1.00              | 318.00  | 20.00      | 254.40  |        |
| M                               | BRACKET-RR BEAM UPR MTG, RH    |                   |     | 1.00              | 9.00    | 20.00      | 7.20    |        |
| M                               | BRACKET-RR BEAM UPR MTG, LH    |                   |     | 1.00              | 9.00    | 20.00      | 7.20    |        |
| M                               | BRACKET-RR BEAM LWR, CTR       |                   |     | 1.00              | 6.00    | 20.00      | 4.80    |        |
| M                               | BRACKET-RR BEAM LWR MTG        |                   |     | 1.00              | 6.00    | 20.00      | 4.80    |        |
| M                               | ANTENNA ASSY-SMARTKEY          |                   |     | 1.00              | 46.00   | 20.00      | 36.80   |        |
| M                               | STAY-RR BUMPER LH              |                   |     | 1.00              | 65.00   | 20.00      | 52.00   |        |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel. 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address   | Owner Name & Vehicle Info   |
|--|---|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #09-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name /ONG JIAN DE<br>Reg No/Reg Date SMH5748Y / 28/01/201<br>Date In/Mileage / 23457<br>Chassis No KNAF3416MK5024748<br>Engine No G4FGJH713608<br>Make/Model KIA/CERATO 1.6 A EX G333<br>Colour/Trim KLG STEEL GREY / WK SATURN BLACK |

| Account No                        | Terms  | Date/Time Printed | CSE        | Operator          | WIP No  |
|-----------------------------------|--------|-------------------|------------|-------------------|---------|
| LAX00000                          | Credit | 12/07/2021/ 19:21 | BLE        | 261 / Edwin Caina | 35995   |
| Description of Goods / Services   |        | Qty               | Unit Price | Disc%             | Amount  |
| M STAY-RR BUMPER RH               |        | 1.00              | 65.00      | 20.00             | 52.00   |
| M COVER-RR BUMPER UNDER, RH       |        | 1.00              | 33.00      | 20.00             | 26.40   |
| M BRACKET ASSY-RR BPR SIDE UPR, L |        | 1.00              | 25.00      | 20.00             | 20.00   |
| M BRACKET-ASSY RR BPR SIDE UPR, R |        | 1.00              | 31.00      | 20.00             | 24.80   |
| M PANEL ASSY-TRUNK LID            |        | 1.00              | 1297.00    | 20.00             | 1037.60 |
| M HINGE ASSY-TRUNK LID, LH        |        | 1.00              | 97.00      | 20.00             | 77.60   |
| M HINGE ASSY-TRUNK LID, RH        |        | 1.00              | 97.00      | 20.00             | 77.60   |
| M PANEL ASSY-BACK                 |        | 1.00              | 324.00     | 20.00             | 259.20  |
| M TRIM ASSY-RR TRANSVERSE         |        | 1.00              | 41.00      | 20.00             | 32.80   |
| M MAT ASSY-LUGGAGE COVERING       |        | 1.00              | 211.00     | 20.00             | 168.80  |
| M W/STRIP-TRUNK LID OPNG          |        | 1.00              | 100.00     | 20.00             | 80.00   |
| M LATCH ASSY-TRUNK LID            |        | 1.00              | 112.00     | 20.00             | 89.60   |
| M STRIKER ASSY-TRUNK LID          |        | 1.00              | 40.00      | 20.00             | 32.00   |
| M LAMP ASSY-REAR COMB INSIDE, LH  |        | 1.00              | 608.00     | 20.00             | 486.40  |
| M LAMP ASSY-REAR COMB INSIDE, RH  |        | 1.00              | 608.00     | 20.00             | 486.40  |
| M LAMP ASSY-REAR COMB OUTSIDE, LH |        | 1.00              | 675.00     | 20.00             | 540.00  |
| M LAMP ASSY-REAR COMB OUTSIDE, RH |        | 1.00              | 675.00     | 20.00             | 540.00  |
| M LAMP ASSY-CENTER GARNISH        |        | 1.00              | 690.00     | 20.00             | 552.00  |
| M FILM-ANTI CHIPPG RH             |        | 1.00              | 27.00      | 20.00             | 21.60   |
| M FILM-ANTI CHIPPG LH             |        | 1.00              | 27.00      | 20.00             | 21.60   |

SURVEYOR NAME :

SURVEYOR SIGNATURE :

DATE :

REMARKS :

Confirm &amp; accepted by Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on **Nett 21004.00** **21,004.00**  
**1470.28**  
**Total Payable 22,474.28**

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                                       |
|---------------------------------|---------------------------------------|
| Date of Submission              | 12/07/2021 12:11 (SGT)                |
| Date of Accident                | 10/07/2021 16:50 (SGT)                |
| Exact Location of Accident      | Woodlands Ave 12, Singapore           |
| Additional Location Information | Beside Mega@Woodland Singapore 737856 |
| Country/State of Loss           | Singapore                             |

### DETAILS OF OWN VEHICLE

|                             |                      |
|-----------------------------|----------------------|
| Vehicle Registration Number | SMH5748Y             |
| INSURED/POLICYHOLDER        |                      |
| Is company?                 | No                   |
| Name Of Registered Owner    | ONG JIAN DE          |
| NRIC No                     | S8848632C            |
| Email Address               | jiande.ong@gmail.com |
| Mobile Phone No             | (Phone) +65-91907507 |
| Alternative Phone No        | +65-91907507         |

### VEHICLE PARTICULARS

|  |             |
|--|-------------|
| Manufacturer   | Kia         |
| Model  | Cerato      |
| Variant  | -           |
| Exact purpose for which vehicle was being used at time of accident           | -           |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes         |
| Vehicle Category   | Private car |
| Transmission   | Auto        |
| CC   | 1591        |

### INSURANCE COMPANY

|                           |                                      |
|---------------------------|--------------------------------------|
| Name of Insurance Company | AIG Asia Pacific Insurance Pte. Ltd. |
| Type of Coverage          | Comprehensive                        |
| Fleet Policy              | No                                   |
| Policy Number             | 1900009095-02                        |
| Cover Note Number         | -                                    |

### DRIVER

|  |                       |
|--|-----------------------|
| Date Of Birth  | 09/12/1988            |
| Occupation   | Indoor                |
| Date Of Driving Pass   | 27/09/2018            |
| Driving experience   | 2 YEARS AND 10 MONTHS |
| Gender   | Male                  |
| Mobile Number  | (Phone) +65-91907507  |
| Alt. Phone Number  | +65-91907507          |
| Email Address  | jiande.ong@gmail.com  |
| Address  | 460 SEGAR ROAD        |
| Address complement   | #03-189 SINGAPORE     |
| Postcode   | 670460                |
| Is the driver the policyholder?                              | Yes                   |
| If No, Relationship of the Driver with the Insured           | -                     |
| Does Driver Own Other Vehicles?                              | No                    |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                     |
| Insurance Company of Other Vehicle Owned by Driver           | -                     |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |                 |
|--------------------|-----------------|
| Type of Accident   | Chain Collision |
| Weather Conditions | Clear           |
| Road Surface       | Dry             |

#### OTHER INFORMATION

|   |     |
|---|-----|
| Was any foreign vehicle involved in the accident?   | No  |
| Number of vehicles involved in the accident   | 2   |
| Was anybody injured in the Accident?  | No  |
| Was any injured conveyed to hospital by ambulance?  | -   |
| Was any other vehicle or property damaged?  | Yes |
| Number of Passengers (Including Driver)   | 2   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |

#### PASSENGER 1

|        |                      |
|--------|----------------------|
| Name   | Elaine Goh Zhen Ying |
| Gender | Female               |

#### DETAILS OF POLICE ACTION

|   |    |
|---|----|
| Was the accident reported to the police?  | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom?                     | -  |

#### CIRCUMSTANCES OF ACCIDENT

SLJ7092C (1st car) stopped. SMH5748Y (Me 2nd car) stopped behind 1st car. SMX2169D (3rd car) hit 2nd car and 2nd car shifted forward and hit 1st car

#### ATTACHMENT(S)

|   |                   |
|---|-------------------|
| Are accident photos available for attachment?     | Yes               |
| Was there any video captured by Car Camera?       | Yes               |
| Reasons for not uploading a video of the accident | NO VIDEO UPLOADED |
| Was there any audio recorded?                     | No                |

#### DETAILS OF OTHER VEHICLE PROPERTY


|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SMX2169D |
| Vehicle Manufacturer        | -        |
| Vehicle Model               | -        |

|   |             |
|---|-------------|
| Vehicle Colour                          | -           |
| Vehicle Category                        | Private car |
| Name of Driver                          | -           |
| Contact Number                          | -           |
| Address                                 | -           |
| Address complement                      | -           |
| Postcode                                | -           |
| Insurance Company Name                  | -           |
| Nature Of Damage                        | -           |
| Details of property damaged in accident | -           |
| No. Of Passenger (Including Driver)     | -           |

#### DETAILS OF OTHER VEHICLE PROPERTY 2

|   |             |
|---|-------------|
| Vehicle Registration Number             | SLJ7029C    |
| Vehicle Manufacturer                    | -           |
| Vehicle Model                           | -           |
| Vehicle Variant                         | -           |
| Vehicle Colour                          | -           |
| Vehicle Category                        | Private car |
| Name of Driver                          | -           |
| Contact Number                          | -           |
| Address                                 | -           |
| Address complement                      | -           |
| Postcode                                | -           |
| Insurance Company Name                  | -           |
| Nature Of Damage                        | -           |
| Details of property damaged in accident | -           |
| No. Of Passenger (Including Driver)     | -           |

SKETCH PLAN







# SINGAPORE POLICE FORCE



T/20210712/7017

1 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20210712/7017

## REPORT OF A TRAFFIC ACCIDENT

|  |            |                              |   |                    |                            |
|--|------------|------------------------------|---|--------------------|----------------------------|
| Date/Time Report Made:<br>12/07/2021 15:16 |            | Vide Report No.:             |   | Station Diary No.: |                            |
| <b>Informant's Particulars</b>             |            |                              |   |                    |                            |
| Name of Informant:<br>ONG JIAN DE          |            |                              | Address:<br>460 SEGAR ROAD #03-189 SINGAPORE 670460 |                    |                            |
| ID Type / ID No.:<br>NRIC NO / S8848632C   |            |                              | Contact No.:<br>Home/Office:                        |                    | Mobile: 91907507           |
| Nationality:<br>SINGAPORE CITIZEN          |            |                              | Email:<br>JIANDE.ONG@GMAIL.COM                      |                    |                            |
| Sex:<br>Male                               | Age:<br>32 | Date of Birth:<br>09/12/1988 | Type of Informant:<br>Driver                        |                    |                            |
| Race:<br>Chinese                           |            |                              | Language:<br>English                                |                    | Institution / School Name: |
| Occupation:<br>Fire and safety inspector   |            |                              | Driving Licence Information:<br>Class: 3            |                    | Date of Expiry:            |

## General Information of the Accident

|  |                  |   |  |                                     |
|--|------------------|---|--|-------------------------------------|
| Type of Accident:  | Injury<br>Others | Drink Drive:<br>No                          | Date/Time of Accident:<br>10/07/2021 17:00 | Type of Location:<br>Straight Road  |
| Location:<br><br>WOODLANDS AVENUE 12                         |                  |   |  |                                     |
| Weather:<br>Clear  |                  | Road Surface:<br>Dry                        |  | Road Speed Limit:<br>70 Km/h        |
| Traffic Flow:<br>One Way                                     |                  | Traffic Control:<br>Traffic Light - Working |  | Traffic Volume:<br>Light            |
| Type of Collision:<br>Between Moving Vehicles - Head To Rear |                  |   |  | Anyone conveyed by ambulance:<br>No |

## Details of Vehicle Involved

| Vehicle No. | Type | Make           | Model                | Color  | Conditio | No of |
|-------------|------|----------------|----------------------|--------|----------|-------|
| SLJ7029C    | Car  | HONDA          |                      | Silver |          | 0     |
| SMH5748Y    | Car  | KIA            | CERATO+1.6%28A%29+EX | Grey   |          | 0     |
| SMX2169D    | Car  | VOLKSWAGO<br>N |                      | Blue   |          | 1     |



**SINGAPORE  
POLICE FORCE**



T/20210712/7017

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

2 of 3

Report No. T/20210712/7017

**CONTINUATION OF REPORT**

| Details of Vehicle Insurance |                                      |               |            |             |
|------------------------------|--------------------------------------|---------------|------------|-------------|
| Vehicle No.                  | Insurance Company                    | Insurance No  | Effective  | Expiry Date |
| SMH5748Y                     | AIG ASIA PACIFIC INSURANCE PTE. LTD. | 1900009095-02 | 28/01/2021 | 27/01/2022  |

| Details of Person Involved        |                      |                                |                                   |                                 |
|-----------------------------------|----------------------|--------------------------------|-----------------------------------|---------------------------------|
| Any Pedestrian Involved: No       |                      |                                |                                   |                                 |
| No. of Pedestrians Injured: NIL   |                      | Use of Pedestrian Crossing: NA |                                   |                                 |
| Passenger                         |                      |                                |                                   |                                 |
| Name                              | GOH ZHEN YING ELAINE |                                | ID No.                            | S8900955C                       |
| Related Vehicle                   | SMH5748Y (Car)       |                                | Contact No.                       | 92385330                        |
| Hospital/Clinic                   | NIL                  |                                | Class of Driving Licence & Expiry | Class: 3<br>Date of Expiry: NIL |
| Date                              | 11/07/2021           |                                | Date                              | 11/07/2021                      |
| No. of Days granted Medical Leave | 03                   |                                | Degree of                         | Slight                          |
| Driver                            |                      |                                |                                   |                                 |
| Name                              | ONG JIAN DE          |                                | ID No.                            | S8848632C                       |
| Related Vehicle                   | SMH5748Y (Car)       |                                | Contact No.                       | 91907507                        |
| Hospital/Clinic                   | NIL                  |                                | Class of Driving Licence & Expiry | Class: 3<br>Date of Expiry: NIL |
| Date                              | 11/07/2021           |                                | Date                              | 11/07/2021                      |
| No. of Days granted Medical Leave | 03                   |                                | Degree of                         | Slight                          |

Brief Details.

Travelling along woodland ave 12 beside Mega@woodland after exiting SLE.

SLJ7029C (1st car) stopped  
SMH5748Y (2nd car, My Car) stopped  
SMX2169D (3rd Car) Hit 2nd car from the rear resulted in chain collision



**SINGAPORE  
POLICE FORCE**



T/20210712/7017

3 of 3

Police Station Of Origin:  
Traffic Police  
10 Ubi Avenue 3 SINGAPORE 408865  
Tel No: 65470000

Report No. T/20210712/7017

**CONTINUATION OF REPORT**

Sketch Plan

Informant is not able to provide sketch

Signature Of Officer Recording The Report:  
Not applicable

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / TPIB /  
TAY CHUN KEEN  
Contact No.: 65476436

Authentication Stamp

Signature Of Informant:  
The identity of the person making this report has  
been authenticated by Singpass. No signature is  
required.

Date/Time:  
12/07/2021 15:16

Classification Of Case: