

## **CYCLE & CARRIAGE KIA PTE LTD** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE** 

Co Reg No : 199405410K	ESTIMATE	GST Reg No : MR-8500111-X
Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/ONG JIAN DE
Ltd.	Reg No/Reg Date	SMH5748Y / 28/01/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 23457
78 SHENTON WAY #09-16	Chassis No	KNAF3416MK5024748
AIG BUILDING SINGAPORE 079120	Engine No	G4FGJH713608
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	
LAX00000	Credit	12/07/2021/ 19:21	BLE	261 / Edwin Caina		35995	
		Description of Good	ls / Service	es .	Qty	Unit Price Disc%	Amount
		N) FR BUMPER , BONNE	T & FR SU	PPORT			2000.00
E PNT88000		R & RHF FENDER	T.D.				4000.00
REPAIR R E PNT98000 RESPRAY	R FLR PNI FRT BUMPE	, RR END PNL & BOOTL _ , LHR FENDER , RH ER , BONNET , LHF FE ND PNL , RR FLR PNL	IR FENDER INDER , RH		t		4200.00
RR CHASS E PNT88000	IS, LHF	DOOR , RHF DOOR & L	HR DOOR		l –		100.00
M SUNDRY		C COND & RADIATOR	SI	imai	[(=	7	80.00
TOP UP A		CONT. I.D. COMPONENT					120.00
E PNT88000		OOTLID COMPONENT	CADDET 0	CEAT			120.00
A 54900099		R FLR BOARD , TRIM ,	CARPET &	SEAT			30.00
A 10028901		CTRICAL SYSTEM	CTDONIC C	ONTDOL CVCTCM			120.00
M SUNDRY		GNOSTIC CHECK ON ELE	CIKONIC C	ONIKOL STSTEM			50.00
M SUNDRY		PLATE WITH CASING					50.00
E PNT88000		PLATE WITH CASING					80.00
TO RENEW M SUNDRY							220.00
SUPPLY RI M SUNDRY							80.00
APPLY AN' M SUNDRY	TI CORROS	SION ON AFFECTED ARE	AS				80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

## **ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name /ONG JIAN DE
Ltd.	Reg No/Reg Date SMH5748Y / 28/01/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage / 23457
78 SHENTON WAY #09-16	Chassis No KNAF3416MK5024748
AIG BUILDING SINGAPORE 079120	Engine No G4FGJH713608
Contact No 64191000	Make/Model KIA/CERATO 1.6 A EX G333
	Colour/Trim KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Pri	inted	CSE	Operator		WIP No		
LAX00000	Credit	12/07/2021/	19:21	BLE	261 / Edwin Caina		35995		
		Description	of Goods	/ Service:		Qty	<b>Unit Price</b>	Disc%	Amount
SUPPLY B	ODY PNL :	SEALANT	-						
M SUNDRY									40.00
SUPPLY C	&C BADGE							1	20.00
M SUNDRY								ļ	30.00
Sundries						1.00	633.00	20 00	506.40
M COVER-FR M GRILLE-F		) ED				1.00	262.00		209.60
M GRILLE-F M GRILLE A						1.00	328.00		262.40
		JMPER ENERGY				1.00		20.00	67.20
M STIFFNER						1.00	114.00		91.20
		R UPR SIDE MT]			П	1.00		20.00	17.60
		R UPR SIDE MT	<u> </u>	$\sim$ 5.7				20.00	17.60
M PANEL AS					ima	1.00	1502.00		1201.60
M BEAM COM		BUMPER		つ) (L	(9)	1.00	7 497.00		397.60
		NT END MODULE				1.00	675.00	20.00	540.00
M ORNAMENT						1.00	32.00	20.00	25.60
M LOGO ASS	Y-KIA SU	3				1.00		20.00	25.60
M EMBLEM-C	ERATO					1.00		20.00	22.40
M COVER-RR	BUMPER					1.00	651.00		520.80
M COVER-RR	BUMPER I	_WR				1.00	241.00		192.80
M COVER-RR	BUMPER I	JNDER,LH				1.00		20.00	26.40
		FOG LAMP,LH				1.00		20.00	15.20
		FOG LAMP,RH				1.00		20.00	15.20
		/SIGNAL,LH				1.00	181.00		144.80
		/SIGNAL,RH				1.00	181.00		144.80
M EXTN WIR		-RM2				1.00	207.00		165.60
M BEAM-RR		IDD MTC DII				1.00	318.00	20.00	254.40 7.20
		JPR MTG,RH				1.00 1.00		20.00	7.20
		JPR MTG,LH				1.00		20.00	4.80
M BRACKET- M BRACKET-		•				1.00		20.00	4.80
M BRACKET- M ANTENNA						1.00		20.00	36.80
M STAY-RR						1.00		20.00	52.00
m SIMIFRE	DUMPER LI	1				1.00	55.00	_0.00	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



# **CYCLE & CARRIAGE KIA PTE LTD** PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

## **ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/ONG JIAN DE
Ltd.	Reg No/Reg Date	SMH5748Y / 28/01/201
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 23457
78 SHENTON WAY #09-16	Chassis No	KNAF3416MK5024748
AIG BUILDING SINGAPORE 079120	Engine No	G4FGJH713608
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
AX00000	Credit	12/07/2021/ 19:21	BLE	261 / Edwin Cair	na	35995		
		Description of Good	s / Services		Qty	<b>Unit Price</b>	Disc%	Amount
M STAY-RR I	BUMPER RE				1.00		20.00	52.00
M COVER-RR		<del>-</del>			1.00		20.00	26.40
		BPR SIDE UPR,L			1.00		20.00	20.00
		BPR SIDE UPR,R			1.00		20.00	24.80
M PANEL AS:					1.00	1297.00		1037.6
M HINGE AS:		•			1.00 1.00		20.00	77.6
M HINGE ASS		LIU,KH			1.00	324.00		259.20
M PANEL AS: M TRIM ASS'		ICVEDCE			1.00	-	20.00	32.8
M MAT ASSY					1.00	211.00		168.80
M W/STRIP-						100.00		80.00
M LATCH AS:		LID	○	ima	1.00	112.00		89.60
M STRIKER		IK LID	$\leq$		1.00	40.00	20.00	32.00
		OMB INSIDE, LH	O) [5]		4.00	608.00	20.00	486.40
M LAMP ASS	Y-REAR CO	MB INSIDE,RH			1.00	608.00		486.40
M LAMP ASS	Y-REAR CO	OMB OUTSIDE,LH			1.00	675.00		540.00
		OMB OUTSIDE,RH			1.00	675.00		540.00
M LAMP ASS					1.00	690.00		552.00
M FILM-ANT					1.00		20.00	21.60
M FILM-ANT	I CHIPPG	LH			1.00	27.00	20.00	21.60
							1	
		SURVEYOR NAM	ΛE:		<b>-</b> :			
		SURVEYOR SIGI	NATURE :		_			
		DATE:			_			
		REMARKS :						
Confirm & a	ccepted b	у						
Confirm & a	ccepted b	у			7% GST on	Ne: 21004.6		•
Confirm & a	ccepted b	y					00	21,004.6 1470.2 22,474.2

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered any aggitional parts or labour which may be required after repair work has commenced. Occasionally work of damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SA01217C0005-01 / AIG Asia Pacific Insurance Pte, Ltd. ENTRY DATE & TIME: 12/07/2021 12:11 (SGT)

SUBMITTED BY: Grace Tan

VERSION: 2 (12/07/2021 16:27 (SGT))



# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate
- policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### ACCIDENT STATEMENT

Date of Submission 12/07/2021 12:11 (SGT) Date of Accident 10/07/2021 16:50 (SGT) **Exact Location of Accident** Woodlands Ave 12, Singapore

Beside Mega@Woodland Singapore 737856 Additional Location Information

Country/State of Loss Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMH5748Y

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner ONG JIAN DE NRIC No. S8848632C

Email Address jiande.ong@gmail.com Mobile Phone No. (Phone) +65-91907507

+65-91907507 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Kia Model Cerato

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Private car

Transmission Auto CC 1591

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

**Policy Number** 

Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.

Comprehensive

1900009095-02

DRIVER

 Date Of Birth
 09/12/1988

 Occupation
 Indoor

 Date Of Driving Pass
 27/09/2018

Driving experience 2 YEARS AND 10 MONTHS

Gender M

Mobile Number (Phone) +65-91907507

Alt. Phone Number +65-91907507

Email Addressjiande.ong@gmail.comAddress460 SEGAR ROADAddress complement#03-189 SINGAPORE

Postcode 670460

Is the driver the policyholder?

Yes

If No, Relationship of the Driver with the Insured

-

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

insurance company of other vehicle owned by briver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Chain Collision

Weather Conditions Clear Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No
Number of vehicles involved in the accident

Was anybody injured in the Accident?

No
Was any injured conveyed to hospital by ambulance?

Was any other vehicle or properly damaged?

Yes

Number of Passengers (Including Driver) 2
Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

PASSENGER 1

Name Elaine Goh Zhen Ying

Gender Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

No
If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

SLJ7092C (1st car) stopped. SMH5748Y (Me 2nd car) stopped behind 1st car. SMX2169D (3rd car) hit 2nd car and 2nd car shifted forward and hit 1st car

ATTACHMENT(S)

Are accident photos available for attachment?

Yes
Was there any video captured by Car Camera?

Yes

Reasons for not uploading a video of the accident NO VIDEO UPLOADED

Was there any audio recorded?

#### **DETAILS OF OTHER VEHICLE PROPERTY 1**


Vehicle Registration Number SMX2169D

Vehicle Manufacturer

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	_
Address	-
Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	-
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	-

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLJ7029C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	: <del>-</del>
Contact Number	
Address	
Address complement	-
Postcode	-
Insurance Company Name	_
Nature Of Damage	
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_







Police Station Of Origin:

Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

1 of 3 Report No. T/20210712/7017

#### REPORT OF A TRAFFIC ACCIDENT

12/07/2021	•		Vide Report No.:		Station Diary No.:		
Informant's Particulars		ars					
Name of Informant: ONG JIAN DE			Address: 460 SEGAR ROAD #03-189 SINGAPORE 670460				
ID Type / ID No.: NRIC NO / S8848632C			Contact No.: Home/Office:	Mobile: 91907507			
Nationality: SINGAPORE CITIZEN		N	Email: JIANDE.ONG@GMAIL.COM				
Sex:         Age:         Date of Birth:           Male         32         09/12/1988			Type of Informant: Driver				
Race: Chinese			Language: English	Institution /	School Name:		
Occupation Fire and sa		otor	Driving Licence Information: Class: 3 Date of Expiry:		oiry:		

General Informati	on of the Accident					
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 10/07/2021 17:00	)	Type of Location: Straight Road	
Location:		·				
WOODLANDS AV	/ENUE 12					
Weather:		Road Surface:		1	d Speed Limit:	
Clear		Dry		70 K		
		Traffic Control: Traffic Light - Working			Traffic Volume:	
Type of Collision: Between Moving	Vehicles - Head To R	ear			one conveyed by ulance:	

Details of Vehicle Involved								
Vehicle No.	Туре	Make	Model	Color	Conditio	No of		
SLJ7029C	Car	HONDA		Silver		0		
SMH5748Y	Car	KIA	CERATO+1. 6%28A%29+ EX			0		
SMX2169D	Car	VOLKSWAGO N		Blue		1		





1202 107 1217017

2 of 3 Report No. T/20210712/7017

Police Station Of Origin: Traffic Police

10 Ubi Avenue 3 SINGAPORE 408865

Tel No: 65470000

#### **CONTINUATION OF REPORT**

Details of Vehicle Insurance							
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date			
SMH5748Y	AIG ASIA PACIFIC INSURANCE PTE.	1900009095-02	28/01/2021	27/01/2022			

<b>Details of Perso</b>	n Involved					
Any Pedestrian I	nvolved: No					
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA			
Passenger						
Name	GOH ZHEN YING ELAINE			ID No.		S8900955C
Related Vehicle	SMH5748Y (Car)			Contact No.		92385330
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: NIL
Date	11/07/2021 Dai		Date	11/07		7/2021
No. of Days gran	ted Medical Leave	Degree of	f Slight			
Driver						
Name	ONG JIAN DE			ID No.		S8848632C
Related Vehicle	SMH5748Y (Car)			Contact No.		91907507
Hospital/Clinic	NIL			Class of Driving Licence & Expiry		Class: 3 Date of Expiry: NIL
Date	11/07/2021 Da		Date	11/07		//2021
No. of Days granted Medical Leave 03			Degree of Sligh		Slight	

### Brief Details.

Travelling along woodland ave 12 beside Mega@woodland after exiting SLE.

SLJ7029C (1st car) stopped SMH5748Y (2nd car, My Car) stopped SMX2169D (3rd Car) Hit 2nd car from the rear resulted in chain collision





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 3 of 3 Report No. T/20210712/7017

#### **CONTINUATION OF REPORT**

Informant is not able to provide sketch

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 12/07/2021 15:16
Officer In Charge Of Case: TP / TPIB / TAY CHUN KEEN Contact No.: 65476436	Classification Of Case:
Authentication Stamp	