



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007587/Kvf3n2 Date: 26/08/2021 Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMG 5445B	Veh. Inspected	SGS 1828P	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010817/JM	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	13/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	JAGUAR XE (A)	c.c	1999	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SAJAB4AN9HCP07027	Colour	METALLID DARK GREEN	
Odometer	39003 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/40 R18	PETLAS	7 mm	
L/H Front Tyre	235/40 R18	PETLAS	7 mm	
R/H Rear Tyre	255/35 R18	PETLAS	7 mm	
L/H Rear Tyre	255/35 R18	PETLAS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	09/07/2021	Inspection Date	15/07/2021	
Survey held at	LIM TAN MOTOR PTE LTD BLK 176 SIN MING DRIVE #03-09 SIN MING AUTOCARE SINGAPORE 575721			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	