

Not Notified
 1/12/21 @ 7950/r
 Return After Rain



5 days

SURVEYOR NAME : Kenneth (Yong)
 DATE OF SURVEY : 15.07.2021
 TIME OF SURVEY : 11am

DATE : 12-Jul-21
 DATE OF ACCIDENT : 09-Jul-21
 THIRD PARTY REF : SMG 5445 B/AUTO & GENERAL

ESTIMATE TO REPAIR

VEHICLE NO. : SGS 1828 P
 MAKE : JAGUAR
 MODEL : XE 2.0 14D TSS
 YEAR : 2016
 CHASSIS NO : SAJAB4AN9HCP07027

No.	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1PC	N/S FRONT DOOR				\$ 3,800.00
1PC	N/S FRONT DOOR RUBBER				\$ 375.00
1PC	N/S FRONT DOOR REGULATOR				\$ 700.00
1PC	N/S REAR DOOR				\$ 4,350.00
1PC	N/S REAR DOOR RUBBER				\$ 375.00
1PC	N/S REAR DOOR REGULATOR				\$ 900.00
2PCS	N/S DOOR HINGE		\$ 180.00		\$ 360.00
1PC	N/S REAR DOOR CHECK				\$ 170.00
1PC	N/S SIDE SKIRT				\$ 2,150.00
1PC	N/S FRONT WHEEL RIM				\$ 2,550.00
	LESS 10%				\$ 15,730.00
					\$ 1,573.00
					\$ 14,157.00
	TO PUTTY & SPRAY PAINT				\$ 1,200.00
	TO CHECK WHEEL ALIGNMENT				\$ 80.00
	TO TRANSFER DOOR FITTING				\$ 100.00
	LABOUR CHARGES				\$ 800.00
TG/TL	TOTAL				\$ 16,337.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721

Tel:65-64520893 Fax:65-64589127

Email: edmund@LTM.sg

Website: www.LTM.sg

Co.Reg No.199307277D

GST Reg No.M2-0019086-0

Document must not be reproduced, in whole or in part, or disclosed to third party or parties without the prior written

Lim Tan Motor Pte Ltd

consent of