

ASS. REC. BY:

Steve

CS/SMR21007594/Euf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TPRES/OD-RES/EVA/INV/MV

To Inspect Vehicle No: SLA 8680L

At Workshop m/s BORNEO MOTORS

Insured: SHC 4613U

Policy No.

Claims No. TAX/07/21/2022


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

SIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Cum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLA 8680L

Yr Regn:

21/3/16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

LEXUS ES 250

c.c.

2494

Colour:

Silver

A/C:

Insured / Std / NI / N

Sp. Reading:

45521

T/Radio:

Insured / Std / NI / N

Eng/No:

C/No:

JTHB1166722090865

Gen. Cond: Good / Fair / Poor / Buipt

Steering: Inorder / Jammed / Locked / Burnt or

Brake: Inorder / Jammed / Locked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

215/55R17

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal:

4

mm

R/Bal:

4

mm

U/Bal:

4

mm

U/Bal:

4

mm

D.O.A.

11/7/21

D.O.A.

16/7/21

Survey held at

Borneo Motors

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

F-R R17

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

NAK-100K

16/7/2021 @4.01m Revise to Ashlene via email.

6/8/2021 Confirm final fig P/P \$3094, 3 repair days. (RED \$9377.10; 75%)

Date/Time, File, Page 107



Prel. Report

Days Of Repair: 3

6/8 TYPIST



Final Report

Resurvey No. of Trip: 2

Survey Fee:

Date/Time, File Return 107

Add Fee:



Site Insp

(\$



Interview

(\$



Tech. Inve

(\$



Weekend

(\$

Transportation:

S + RS \$

Private

Others

TOTAL

Amount Owed:

JP

Amount Owed:

\$3094



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No.2 Pandan Crescent
Singapore 128462, Tel no.: 6631 1388

Steve CLKK)
83228813

Stevechen@CLKKauto.com

Mr AL

3 dys

PIP

My BL by



ESTIMATE

16/7/21, 11.00am

Account Details	Account No.	Customer Details
THIRD PARTY CLAIM <i>TP - First Capital</i> <i>Survey on 16/7/21 11am</i> <i>LKK Sumner</i>	S1000020 / TPCLAIM Document No. 0 Document Date 12/07/2021	Ms Deng Yan 72 Bayshore Road #13-15 Singapore 469988 Mobile: 96644580

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASV60R	BETGK L3	21/03/2016	SLA8680L	0	19899	64TP/SLA8680L/110721

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHBJ1GGX02090565	2ARF160069	60	Wally Tan G H	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.: ACC DATE: TOW/DRIVE IN: EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				50 80.00
2	B	BP-LAB3 CHECK WIRING SYSTEM AND FOCUS HEADLAMP. (NETT)				216.50
3	B	BP-LAB3 REMOVE/REFIX FRONT PRKING SENSORS. (NETT)				216.50
4	B	BP-LAB3 REMOVE/REFIX FRONT BUMPER COVER AND REALIGN.				866 1082.50
5	B	BP-RES3 SPRAY PAINT ON FRONT BUMPER COVER.				747 927.50
6	B	BP-ECU3 TO RESET ECU & REPROGRAMME. (NETT)				216.50
7	L	BP-LPO SUPPLY REGN PLATE (PO#) FRONT (NETT)				96.00
8	1	L81105-33D10 HOUSING SUB-ASSY, HEADLAMP, RH	1.00	6185.20		6185.20
9	2	L53121-33080 MOULDING, RADIATOR	1.00	375.80		375.80
10	3	L52145-33070 STAY, FR BUMPER	1.00	58.00		58.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

Co. Reg No. : 196700086Z
 GST Reg No. : MR-8500000-9
 No 2 Pandan Crescent
 Singapore 128462, Tel no. : 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		Ms Deng Yan		
			Document No. 0		72 Bayshore Road #13-15 Singapore 469988		
			Document Date 12/07/2021		Mobile: 96644580		
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ASV60R	BETGK L3	21/03/2016	SLA8680L	0	19899	64TP/SLA8680L/110721
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHBJ1GGX02090565		2ARF160069	60	Wally Tan G H	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
11	4	L52146-33070 STAY, FR BUMPER	1.00	58.00		58.00	
12	5	L52611-33280 ABSORBER, FR BUMPER	1.00	155.90		155.90	
13	6	L53155-33060 SEAL, RADIATOR	1.00	101.50		101.50	
14	7	L52119-3T910 COVER, FR BUMPER	1.00	968.20		968.20	
15	8	L81481-33060 COVER, FOG LAMP, RH	1.00	143.30		143.30	
16	9	L53102-33080 GRILLE SUB-ASSY,	1.00	885.70		885.70	
17	0	L52114-33450 BRACKET, FR BUMPER	1.00	143.20		143.20	
18	1	L47749-50090 CLIP	2.00	1.80		3.60	
19	2	L53879-30040 RETAINER, FR FENDER	2.00	12.40		24.80	
20	3	L89348-78020 RETAINER, ULTRASONIC	2.00	16.40		32.80	
21	4	L89348-35030 CLIP, ULTRASONIC	2.00	4.40		8.80	
22	5	L89341-78010 B2 SENSOR, ULTRASONIC,	1.00	490.80		490.80	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

For & on behalf of Borneo Motors (Singapore) Pte Ltd		Customer's Signature		Charge Summary		Total 12,471.10	
Acknowledged by Repairer		Please acknowledge receipt of vehicle		Parts 9,635.60 Labour 2,739.50 Sublet 96.00 Lubrication/Fluid 0.00 Others 0.00		GST 7.00% 872.98 Less 0.00 Amount Due 13,344.08	

Customer Copy

SB0G217C000C / Borneo Motors Pte Ltd
ENTRY DATE & TIME: 12/07/2021 16:05 (SGT)
SUBMITTED BY: Ashlyn Chng
VERSION: 1 (12/07/2021 16:05 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	12/07/2021 16:05 (SGT)
Date of Accident	11/07/2021 11:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	87 MARINE PARADE CENTRAL HDB OPEN CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA8680L
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	DENG YAN
NRIC No	SXXXX957E
Email Address	YANMICHELLE365@GMAIL.COM
Mobile Phone No	(Phone) +65-96644580
Alternative Phone No	(Home) +65-96644580

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Es250
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	2500

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	GA449759
Cover Note Number	-

DRIVER

Name of Driver	DENG YAN
NRIC No	SXXXX957E

Date Of Birth	09/11/1981
Occupation	Indoor
Date Of Driving Pass	09/03/2011
Driving experience	10 YEARS AND 4 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96644580
Alt. Phone Number	(Home) +65-96644580
Email Address	YANMICHELLE365@GMAIL.COM
Address	72 BAYSHORE ROAD #13-15
Address complement	-
Postcode	469988
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED SKETCH PLAN AND STATEMENT.

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY:

Vehicle Registration Number	SHC4613U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Taxi
Name of Driver	ZENG RUIFENG
NRIC No	SXXXX532F
Contact Number	(Phone) +65-82280213
Address	-

Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
-
-
-

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the G.I. Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will also be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
 - understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore (GIA) may be permitted to collect, use, disclose and/or process my personal data/personal information set out in this Form and any other personal information provided by me or possession by my insurer collectively the "Personal Information" and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in the accident and insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers", the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims, including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes, mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
 - (b) all insurer(s) who have insured vehicle(s) involved in the accident and the insurers' lawyers/law firms may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may also be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be based outside of Singapore, for one or more of the above Purposes.

Dan Kan
 Policyholder's Signature / Date & Time
 Sketch Plan

 Drivers Signature (if driver is not the policyholder) / Date & Time

 Witnessed by Reporting Centre Personnel



Describe Circumstances of the Accident

On 11.7.2021 at about 9:00 am, I send my son to Learning Lab for Auction at 87 Marine Parade Central. I have parked my car at HDB open car park in the parking lot and left for marketing. After returning to retrieve my car I noticed a piece of paper stick onto my driver's door handle, and also discovered that my car front right side bumper is damaged. The paper written the mobile of other party driver's contact, so I called him (Zeng Ruifeng) immediately and he admitted that he is the one who hit my car and ask me to claim his company (SWAT) insurance.

Declaration

We declare the foregoing particulars are true in every respect

Danifan
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel