

ASS. REC. BY:

GCL

GT

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

RC Auto

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

3

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: Bicycle

Yr Regn: 2018

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

bicycle

Make:

Cervelo Customise

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SNP2D17E.00119

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

700C x 25

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

21PP

Front

Rear

R/Bal.

1

mm

R/Bal.

1

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

13-07-21

Survey held at

W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

and

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$



Interview (\$



Tech. Insp (\$



Meal (\$

S + RS, SI

Photos

Others

Report Format:

Lump Sum / 10 Days

ESTIMATE RC AUTO

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

OWNER:SPARK S NG KEE TIAN

Date : 13.07.2021

Brady & Rotor

700C X 25

[illegible]

Received the above goods in good order and condition

for **RC AUTO**

-20%: 11k

Received by

E.&O.E.

Authorised Signature



**SINGAPORE
POLICE FORCE**



G/20210711/7009

1 of 2

POLICE REPORT (NP299)

Report No. G/20210711/7009

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 11/07/2021 11:16	Vide Report No.	Station Diary No.
Name Of Informant SPARKS NG KEE TIAN	Address 17 FLORA ROAD #07-01 SINGAPORE 509735	
ID Type / ID No. NRIC NO / S6823477H	Contact No. Home/Office:	Mobile: 98282422
Nationality SINGAPORE CITIZEN	Email Address SPARKS777NGK@YAHOO.COM.SG	
Occupation Commercial airline pilot	Sex Male	Age 53
Institution/School Name	Date of Birth 23/06/1968	Race Chinese
Date/Time Of Incident 10/07/2021 20:00 - 10/07/2021 20:05	Location Of Incident PASIR RIS CENTRAL	

Brief details.

I was cycling along Pasir Ris Dr1 heading west on the inner left lane, while approaching junction of St51, with the traffic light green in my favor, I proceeded.

As I entered the junction, I observed a car in opposite direction making a right turn into my path with no intention of stopping at all.

I braked but to no avail, the car just kept coming towards me.

Though my bike is equipped with bright flashing headlights, the driver claimed he did not see me at all. Passerby alerted/called for ambulance and Traffic Police.

Paramedics had an initial assessment of my injury (neck, knee, wrist, finger and head), and after TP

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 11/07/2021 11:16
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp



**SINGAPORE
POLICE FORCE**



G/20210711/7009

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20210711/7009

arrived and took a short report, I was then sent to CGH for CT scans/Xrays.
After all the necessary scans and bodily checks (detail of injuries with CGH), I was discharged at about
midnight, and was given 01 day MC.

Subjects Involved				
Victim				
Person Name	SPARKS NG KEE TIAN		ID No	S6823477H
ID Type	NRIC NO		Age	53
Gender	Male		Language	English
Race	Chinese		Address	17 FLORA ROAD #07-01
Occupation	Commercial airline pilot			SINGAPORE 509735
Mobile No	98282422		Is Informant A Victim?	Yes
Person Name	SPARKS NG KEE TIAN (Informant)			

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 11/07/2021 11:16
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp