

GBK26156, 2020 March.

TP Ching

Nissan NV200 1597cc

Xiao Chen.

VM20138661

Front RH Fender. Dented 504.70 ✓

Front RH Fender Inner Shield torn 188.40 ✓

Front RH Fender Inner Shield clips. 30(SN) ✓

Front RH Fender Glass Sealant. 30(SN) ✓

Front RH Wheel Rim Cover. 80(SN) ✓

693.10 S.N: 60

623.79

Panel Bending

Spray Painting.

Wiring.

To perform wheel alignment. 150. X

~~400~~ 200

~~300~~ 200

~~50~~ 30

430

total: 1113.79

4/5: 900

02 days.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: