

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |   |  |                 |                    |  |
|---|---|--|-----------------|--------------------|--|
|   | CHINA TAIPING IN                        | SURANCE (S) PTE LTD  | Ref:            | CS/CTI21007624/Dvc |  |
|   | 3 ANSON ROAD #<br>SPRINGLEAF TOV        | 16-00<br>VERSINGAPORE 079909   | Date            | e: 14/07/2021      |  |
|   |   |  | Cod             | e: CTI             |  |
| 1.  | Policy Particulars :- THIRD PARTY CLAIM |  |                 |                    |  |
|   | Insured Veh.                            | YP 8313P   | Veh. Inspected  | SMZ 510D           |  |
|   | Policy No.                              |  | Coverage (\$)   | 0.00               |  |
|   | Claim No.                               | SNM21D203847/C02/YP8313P/<br>CHEESC                                    | Excess (\$)     | 0.00               |  |
|   | Assign From                             | CHEE SO CHOW   | Assign Date     | 14/07/2021         |  |
| 2. Vehicle Particulars & Condition  |   |  |                 |                    |  |
|   | Make & Model                            |  | c.c             | 0                  |  |
|   | Engine No.                              | HIDDEN   | Year of Reg.    |                    |  |
|   | Chassis No.                             |  | Colour          |                    |  |
|   | Odometer                                | -  | Steering        |                    |  |
|   | Brakes                                  |  | Modification    |                    |  |
|   | General                                 |  |                 |                    |  |
| 3. Conditions of Tyres  |   |  |                 |                    |  |
|   |   | Size   | Make            | Balance            |  |
|   | R/H Front Tyre                          |  |                 | mm                 |  |
|   | L/H Front Tyre                          |  |                 | mm                 |  |
|   | R/H Rear Tyre                           |  |                 | mm                 |  |
|   | L/H Rear Tyre                           |  |                 | mm                 |  |
| 4.  | Description of Damages                  |  |                 |                    |  |
|   |   |  |                 |                    |  |
| 5.  | 5. General Information                  |  |                 |                    |  |
|   | Accident Date                           | 10/07/2021   | Inspection Date | 14/07/2021         |  |
|   | Survey held at                          | JWG INTERNATIONAL PTE LTD  |                 |                    |  |
|   |   | 10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047 |                 |                    |  |
| 5a.   | 5a. Remarks                             |  |                 |                    |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |   |  |                 |                    |  |