

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE I	PTE LTD		Ref:	CC4/ASM21007635/Npa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	05/09/2022	
	ATTN:KHOR SAW	THENG		Code:	ASM	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SMH 4087C	Veh. Inspected		SFP 96T	
	Policy No.	P2435956	Coverage (\$)		0.00	
	Claim No.	S1M03DKD	Excess (\$)		0.00	
	Assign From		Assign Date		14/07/2021	
2. Vehicle Particulars & Condition						
	Make & Model	NISSAN NOTE 1.2 CVT	c.c		1198	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	JN1TAAE12Z0980002	Colour		WHITE	
	Odometer	35621 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	185/65 R18	CONTINENTAL		5 mm	
	L/H Front Tyre	185/65 R18	CONTINENTAL		5 mm	
	R/H Rear Tyre	185/65 R18	CONTINENTAL		5 mm	
	L/H Rear Tyre	185/65 R18	CONTINENTAL		5 mm	
4.	. Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/07/2021	Inspection Dat	e	14/07/2021	
	Survey held at	ey held at AP AUTOMOTIVE SERVICES PTE LTD				
		9006 TAMPINES ST 93 #01-202 TAMPINES INDUSTRIAL PARK A SINGAPORE 528840				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					
		<u> </u>	·			