

Your Ref: PYK/JO1/966376.Income

Date: 15th Sep 2021

Our Ref: CS1/LAW21007671/R1qf3e2

M/s R. S. Solomon LLC

300 Beach Road The Concourse

#12-02/03/04

Singapore 199555

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SJM 2756C

INSURED VEHICLE: GBA 2110X

ACCIDENT DATE: 07/09/2018

We thank you for your instruction on 15/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SJM 2756C from M/s Absolute Appraisal Services Pte Ltd.
- b) Survey report by FormTeam Consultancy Pte Ltd with colour photographs.
- c) Colour damaged vehicle photographs of SJM 2756C.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SJM 2756C
Make & Model	: Toyota Vios J (A)
Chassis Number	: MR053HY9305089735
Year of Registration	: 2008
Engine Capacity	: 1497 cc

2. We recommend that the repairs of the entire damage require about 8 (Eight) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.