

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	SOMPO INSURAN	CE SINGAPORE PL	Ref:	CS/SMO21007696/Uqf3n2	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623	Date:	26/07/2021	
			Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJM 9628T	Veh. Inspected	SMD 5617M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	CMTD2102091/IJH	Excess (\$)	0.00	
	Assign From	GRACE TEO	Assign Date	15/07/2021	
2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NOTE (A)	c.c	1198	
	Engine No.	HIDDEN	Year of Reg.	2018	
	Chassis No.	JN1TAAE12Z0982070	Colour	PINK	
	Odometer	25522 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	FAIR			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	185/65 R15	CONTINENTAL	8 mm	
	L/H Front Tyre	185/65 R15	CONTINENTAL	8 mm	
	R/H Rear Tyre	185/65 R15	CONTINENTAL	8 mm	
	L/H Rear Tyre	185/65 R15	CONTINENTAL	8 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE D	AMAGES SEE DETAILS.			
5.	General Information				
	Accident Date	13/07/2021	Inspection Date	16/07/2021	
	Survey held at	SIN HWEE MOTOR PTE LTD			
	BLK 3023-A UBI ROAD 1 #01-59 SINGAPORE 408717				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 5 Working Days				