

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21005818/Evce2-1	
	8 SHENTON WAY AXA TOWERSING			Date:	05/08/2021	
	ATTN: TAN WANC	ONG		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)					
	Insured Veh.	SJE 6339P	Veh. Inspected	d	SGS 1238S	
	Policy No.	GA442917/1	Coverage (\$)		0.00	
	Claim No.	S1M03A2P	Excess (\$)		0.00	
	Assign From	TAN WANCONG	Assign Date		16/07/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	B.M.W. 520I	c.c		1998	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	WBAJA12070BJ19136	Colour		GREY	
	Odometer	24683 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	245/45 R18	PIRELLI		5 mm	
	L/H Front Tyre	245/45 R18	PIRELLI		5 mm	
	R/H Rear Tyre	245/45 R18	PIRELLI		5 mm	
	L/H Rear Tyre	245/45 R18	PIRELLI		5 mm	
4.	4. Description of Damages					
	THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.					
	REPAIR CONDITION SEE DETAILS.					
5.	General Information					
	Accident Date	14/05/2021	Inspection Date	te	22/07/2021	
	Survey held at	ENG SOON PAINTING SVC				
		BLK 4 YEW TEE IND EST 393 - WOODLANDS ROAD SINGAPORE 677969	J			
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					