

ASS. REC. BY:

REF: C72/210077081Kt

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_

Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_

Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_

Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_

04

days

Res.: Yes or No

Lum Sum: \_\_\_\_\_

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

07/22

Date: \_\_\_\_\_

Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: \_\_\_\_\_

SGW 36422 Yr Regn: 07 07

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: \_\_\_\_\_

Honda Civic c.c. 1799

Colour: \_\_\_\_\_

White

A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_

188151

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

JHMF016307S215644

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modl: Nil / S/Rlm / STD A/Rlm or \_\_\_\_\_

Tyre Size: \_\_\_\_\_

F: Kapsen 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. \_\_\_\_\_

mm

R/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

L/Bal. \_\_\_\_\_

mm

D.O.A. \_\_\_\_\_

14/7/21

D.O.I. \_\_\_\_\_

16/7/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or \_\_\_\_\_

C/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

FINALISE LUMP SUM \$2600, 4DAYS

RED: 1799.17; 40%

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair: 4

1)

☐

: Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2)

Add Fee: \_\_\_\_\_

: Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

S + RS. \$ \_\_\_\_\_

Fees \_\_\_\_\_

Others \_\_\_\_\_

TOTAL

Report Format :

Lump Sum / I.B.I. (\$ \_\_\_\_\_)



**S&H Motor Pte Ltd**  
**160 Sin Ming Drive #07-02**  
**Sin Ming Autocity**  
**Singapore 575722**

Insurer Reference:  
 Repairer Reference: 042265  
 Date calculated: 15/07/2021 6:09 PM

**Full Report**  
**Registration: SGW3642Z**  
**Printed: 15/07/2021 6:10 PM**

### Summary Information

<b>Claim</b>		<b>Work Provider:</b>	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	14/07/21
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

### Vehicle Details

**Vehicle**  
 Manufacturer: HONDA  
 Model: CIVIC (FD)  
 Sub Model: BASE MODEL  
 Model Sheet Number: 35 48 01  
 Registration: SGW3642Z  
 VIN number:  
 Odometer:

#### Model Specs

AUTO AIR CON	ELECT FOLDING MIRROR	XENON HEADLAMPS	FOG LAMPS
RAIN SENSOR	PAINTED DOOR MIRRORS	LEATHER STRG WHEEL	ANTI THEFT ALARM
1.8 LTR 103 KW	AUTO GEARBOX 5 SPEED	TYRES 215/45 VR 17	WHEELS 4T X 15
ELECTRIC SUNROOF	MUDFLAP	TWO COAT METALLIC	PREPARE OFF VEHICLE

*Not Notch in*  
*L/Ring &*  
*Assembly After Paint*  
*4 days*

### Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RUST PROOFING BODY SHELL PART		2.0	8.40
NO NUMBER	FRONT BUMPER CARRIER RUST PROTECT PROOF		1.0	4.20
NO NUMBER	R + R BOTH FOG LAMPS		2.0	8.40
71125-SNB)	R + R RADIATOR GRILLE BRACKET		1.0	4.20
17SNA-601	RENEW BONNET		6.0	25.20
	INCLUDES: R + R AND ADJUST BONNET			
76841-SNB)	R + R FRONT WIPER RESERVOIR (BUMPER REMOVED)		2.0	8.40
38100-SJD	R + R LOW TONE HORN		5.0	21.00
38150-SLA	R + R HIGH TON HORN		5.0	21.00
60261-SNB	R + R L/F WING		12.0	50.40
	INCLUDES: R + R FRONT BUMPER, HEADLAMP AND WHEELHOUSE COVER			
60260-SMG	R + R R/F WING (BUMPER REMOVED)		9.0	37.80
	DOES NOT INCLUDE: R + R WHEELHOUSE COVER AND HEADLAMP			



Code	Description	WU	Price SGD
60400-SNB	RENEW FRONT PANEL CPL	26.0	109.20
19010-RNA)	R + R RADIATOR CPL WITH ATTACHED PARTS	14.0	58.80
80110-SNA)	R + R AIR CONDITIONING CONDENSER	2.0	8.40
NO NUMBER	REFILL + VENT AIR CONDITIONING	8.0	33.60
1482	RIGHT FRONT DOOR REPAIR	~ 5.0*	21.00
0340	FRONT BUMPER SUPPORT CAVITY PROTECTION		
<b>Labour Cost</b>		<b>Hrs</b>	<b>WU</b>
<b>Panel / Mechanical Labour</b>		9.70	97.0
<b>Total of Labour</b>			407.40

## Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	17.0
	R/F WING NEW PART PAINTING	11.0
	FRONT PANEL CPL SURFACE PAINT	6.0
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	FRONT BUMPER NEW PART PAINT K1G/P	26.0

## Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	47.47
0742	R/F WING NEW PART PAINTING	23.22
1009	FRONT PANEL CPL SURFACE PAINT	11.95
1482	RIGHT FRONT DOOR NEW PART PAINTING	42.83
0283	FRONT BUMPER NEW PART PAINT K1G/P	100.80

## Labour Cost - Paint

Factor	Hrs	WU	Price SGD
Time Paint		75.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
<b>Total</b>	<b>10 WU/h</b>	<b>10.80</b>	<b>108.0</b>

## Material Cost - Paint

	Price SGD
New Part Painting	113.52
New Part Painting - Plastic K1G/PUR	100.80
Surface-/Blend Paint	11.95
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
<b>Total</b>	<b>267.57</b>

## Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
------	-------------	-------------	-------------	----------------------------	-----------



Code	Description	Part Number	Part Source	Price SGD	
0283	FRONT BUMPER	04711SNB010ZZ	Original	my car 240.00	✓
0318	R/F OUT BUMPER BRKT	71193SNB003	Original	cm 25.00	✓
0320	R/F UPP BUMPER BRKT	71140SNB000	Original	28.00	
0340	FRONT BUMPER SUPPORT	71130SNAU90ZZ	Original	R 190.00	X
0410	RADIATOR GRILLE TRIM	71122SNB003	Original	In car 80.00	X
0411	GRILL BRACKET	71125SNB000	Original	cm 115.00	✓
0412	GRILLE	71121SNB003	Original	na 70.00	✓
0431	GRILLE BADGE	75700S9AG00	Original	na 25.00	✓
0471	BONNET	60100SNB000ZZ	Original	R 350.00	X
0492	BONNET LOCK	74120SNBE11	Original	R 75.00	X
0562	R/F HEADLAMP CPL	33101SNBD61	Original	R 290.00	✓
0742	R/F WING	60211SNB000ZZ	Original	R 180.00	✓
0842	R/WHEELHOUSE SHELL	74101SNAA10	Original	D 80.00	✓
1009	FRONT PANEL CPL	60400SNBN01ZZ	Original	R 380.00	X
4465	CONDENSER	80110SNBA43	Original	na 450.00	✓
4492	R/CONDENSER BRACKET	80115SNAA00	Original	R 60.00	✓
7761	RADIATOR	19010RNAJ51	Original	420.00	7
1000	BONNET STAND CLIP	BONNET	Original	na 5.00	✓
f: OEM Parts				Savings	0.00
n: Non-OEM Parts				Subtotal	3,063.00
u: Used parts				Fixed Sundry Parts Price	100.00
<b>Total</b>					<b>3,163.00</b>

### Extras

Code	Description	Price SGD
1001	Electrical work Electrical work	na 15.00*
1002	Engine coolant Engine coolant	na 30.00*
1003	Air con coolant Air con	50.00*
<b>Total Extras</b>		<b>95.00</b>

**LIK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## Final Calculation

	SGD	SGD
<b>Parts</b>		
Fixed Sundry Parts Price	3,063.00	
<b>Total Parts</b>	100.00	<b>3,163.00</b>
<b>Labour Time Base 10 WU/h</b>		
Total 97.0 WU X 42.00 SGD/h	407.40	
<b>Total of Labour</b>		<b>407.40</b>
<b>Additional Costs</b>		
Rustproofing		
Rate 3.0 WU X 42.00 SGD/h	12.60	
<b>Total Of Additional Costs</b>		<b>12.60</b>
<b>Total Of Extras</b>		<b>95.00</b>
<b>Paint Work Time Base 10 WU/h</b>		
Labour Cost 108.0 WU X 42.00 SGD/h	453.60	
Material Cost	267.57	
<b>Total Paint Including Material</b>		<b>721.17</b>
<b>Repair Cost Excludes GST</b>		<b>4,399.17</b>
GST (+7.0%)		<b>307.94</b>
<b>Repair Cost Included GST</b>		<b>4,707.11</b>

## Comments

\* - USER SUPPLIED DATA  
NN - NO MANUFACTURERS CODE EXISTS  
) - WU PARTIAL INCL IN OTHER POSITIONS

## Assessment Note

No assessment notes entered.



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 15/07/2021 16:23 (SGT)  
Date of Accident ..... 14/07/2021 15:55 (SGT)  
Exact Location of Accident ..... Chander Rd, Singapore  
Additional Location Information ..... car park no : TPBKE9 Blk 668 Chander Road  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SGW3642Z

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... Hiang Boon Fong  
NRIC No ..... SXXXX897G  
Email Address ..... joycehiang@gmail.com  
Mobile Phone No ..... (Phone) +65-90224077  
Alternative Phone No ..... (Home) +65-90224077

#### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Civic  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1799

#### INSURANCE COMPANY

Name of Insurance Company ..... Lonpac Insurance Bhd  
Type of Coverage ..... ThirdPartyFireTheft  
Fleet Policy ..... No  
Policy Number ..... Z21VP05029478  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... Toh Teck Bee  
NRIC No ..... SXXXX878J



## SKETCH PLAN

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

### Sketch Plan



A - SGW36422

B - GAK5716A