

ASS. REC. BY:

REF:

TIL /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s Chay 1700

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: ?

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$39k

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBD 6748S Yr Regn: 03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)Make: Toy Dyna C.C. 2982Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 134086 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JT1A735Y30K204153Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rim / STD A/Rim orTyre Size: F: 195R15X8R: 155R12X8(D)BS: OUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 8 mm R/Bal. 77 mmL/Bal. 8 mm L/Bal. 77 mmD.O.A. 14/7/21 D.O.I. 16/7/2021Survey held at ✓

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

157 d/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____) S + RS. \$ _____☐ : Interview (\$ _____) Fines _____☐ : Tech Invs (\$ _____) Others _____☐ : Weekend (\$ _____) _____

TOTAL

Report Format :

Lump Sum / I.B.I: (\$ _____)

GBD 6748S

OD/India

REPAIR DETAILS**Reference**

Part Source: (Last Synchronised: 16 Jul 2021)

Parts: N/A TOYOTA DYNA 150 3.0 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Cheng Hoe Motor Pte Ltd/GBD6748S/16/07/2021 10:33

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*1 PC RH HEADLAMP	0.00	0.00	*340.00 F
2	1		*1 PC FRT RH CORNAL PANEL	0.00	0.00	*80.00 F
3	1		*1 PC FRT RH CORNAL GARNISH	0.00	0.00	*55.00 F
4	1		*1 PC FRT GRILLE	0.00	0.00	*155.00 F
5	1		*1 PC FRT GRILLE LOGO	0.00	0.00	*35.00 F
6	1		*1 PC FRT GRILLE RUBBER	0.00	0.00	*30.00 F
7	1		*1 PC FRT RH DOOR INNER FRT RUBBER	0.00	0.00	*28.00 F
8	1		*1 PC FRT PANEL EMBLEM (DYNA)	0.00	0.00	*32.00 F

F=Franchise part.

Sub Total (\$\$)	755.00
+ Margin on L,N Items 10.00% (\$\$)	75.50
Total Parts (\$\$)	830.50

Cheng Hoe Motor Pte Ltd/GBD6748S/16/07/2021 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS**Estimates on Miscellaneous Items**

No	Qty	Particulars	Amount
1	1	1 PC RH COY STICKER	20.00
2	1	OD/TP Case (Insurer)	11.00

Miscellaneous Items

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Sub Total (\$\$) 31.00


Estimates on Labour

No	Particulars	Lab.Type	Amount
1	REMOVE & REFIX FRT BUMPER, GRILLE, HEADLAMP, KNOCK & REPAIR FRT RH W/SCREEN PILLAR, FRT RH DOOR & REALIGN THE SAME	New	600.00
2	PUTTY & RESPRAY ON FRT BUMPER, FRT RH DOOR, W/SCREEN PILLAR, FRT PANEL, GRILLE	New	600.00

Gross Labour Cost (\$\$) 1,200.00

Cheng Hoe Motor Pte Ltd/GBD6748S/16/07/2021 10:33. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761

Tel : 67556142 Fax : 67557719

Email: chmotor@singnet.com.sg

INSURER: India International Insurance Pte Ltd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/INDIA
Policy No:	D19MCV0001427-02	Date of Loss:	14/07/2021
Vehicle Reg. No.:	GBD6748S	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	ENG TIONG LEE PTE LTD		
Driver:	CHEW HOCK HWEE		
Make/Model:	TOYOTA DYNA 150, 3.0 D (M)	Vehicle Reg. Date:	10/03/2015
Vehicle Colour:	SILVER		
Engine No:	1KD2473787	Chassis No:	JTFAT35Y30K204153
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	0		
Description of Accident/Loss	REFER TO GIA REPORT ATTACHED.		
Remarks:	VEHICLE CURRENTLY LYING AT YISHUN WORKSHOP.		
Present Location:	CHENG HOE MOTOR PTE LTD (YISHUN)		

Not Authorize
11 Sep 21
Repair After Repair
4 days

COST OF CLAIMS	Amount
Parts	830.50
Miscellaneous Items	31.00
Labour	1,200.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	2,061.50
+ GST 7.00% (S\$)	144.31
Nett Amount (S\$)	2,205.81

This claim is handled by: SHARON CHIONG BENG CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

> Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	723G

Vehicle Details

Vehicle No.:	GBD6748S
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jul 2021
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2014
Engine No.:	1KD2473787
Chassis No.:	JTFAT35Y30K204153
Maximum Power Output:	-
Open Market Value:	\$27,856.00
Original Registration Date:	10 Mar 2015
First Registration Date:	10 Mar 2015
Transfer Count:	1
Actual ARF Paid:	\$1,393.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	09 Mar 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$37,741.00
COE Rebate Amount:	\$13,761.00
Total Rebate Amount:	\$13,761.00

The information contained herein is correct as at 15 Jul 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 15/07/2021 14:19 (SGT)
Date of Accident 14/07/2021 16:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE(TUAS SLIP RD) TWDS TUAS CHECKPOINT AT
Country/State of Loss ROUNDABOUT
Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBD6748S

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner ENG TIONG LEE PTE LTD
Company Reg No 2XXXXX723G
Email Address hhchew.etl@gmail.com
Mobile Phone No (Phone) +65-97654879
Alternative Phone No +65-97654879

VEHICLE PARTICULARS

Manufacturer Toyota
Model Dyna
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Commercial vehicle
Transmission Manual
CC 2982

INSURANCE COMPANY

Name of Insurance Company India International Insurance Pte Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number D19MCV0001427-02
Cover Note Number 10/03/21 - 09/03/22

DRIVER

Name of Driver CHEW HOCK HWEE

Sketch Plan

PIE (Tuas Slip Rd)

A: GBD 67485
B: SLG 9847K (PHV)
Quah Siat Meng
S6930956I

point

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was moving in the 2nd lane at the above roundabout towards Tuas Checkpoint when car B moving at my right (lane 3) suddenly cut into my lane as he was heading towards Pioneer Road. As a result, car B left rear collided onto the front right of my vehicle. No one was injured.

Note : Please note that your insurer may have 14 days Time Frame for you to submit an Own Damage Claim under your own comprehensive policy. Please check with your policy for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

Full

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: / (Ys)
NRIC/FIN No.:

15/7/21