

ASS. REC. BY:

REF: CS/

SMR / 21007724 / Kuf3

Kenneth

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: SLP 4929T

at Workshop m/s Cheng Hoe

of \_\_\_\_\_

Insured: SHD 6277M

Policy No. \_\_\_\_\_

Claims No. TAX/07/21/2028

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or No

Lum Sum: 1-B-1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SLP 4929T Yr Regn: 03, 19

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA

Make: Honda Fit c.c. 1317

Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading: 19522 T/Radio: Insured / Std / Nil / NA

Eng/No: \_\_\_\_\_

C/No: GK3 . 1343822

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / SRM / STD A/Rlm or

Tyre Size: F: 175/70R14

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front: \_\_\_\_\_ Rear: \_\_\_\_\_

R/Bal. 2 mm R/Bal. 3 mm

L/Bal. 2 mm L/Bal. 3 mm

D.O.A. 11/7/21 D.O.I. 21/7/2021

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S/N

The U/C / Chassis frame / Body Structure affected due to collision.

OPC

Date / Time Action / Instruction

Confirmed P/P \$1493.36, 3 repair days  
(RED \$288.48; 16%)

Date/Time, File Pass to?

: Prell. Report

: Final Report

11/7/12 TYPIST

Date/Time, File Return to?

Days Of Repair: 3

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:  : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Report Format: TP

ump Sum / I.B.I: (\$ \$1493.36)

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761  
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg  
 GST:201001158E RCB NO:201001158E

SLP4929T  
 TP/SMRT

M/S : SMRT AUTOMOTIVE SERVICES PTE LTD  
 60 WOODLANDS INDUSTRIAL PARK E4  
 SINGAPORE 757705

TEL: 64823888  
 ATTN: Motor Claim Department

FAX: 63687421

WS Ref: TP/SMRT  
 Claim Type: Third Party  
 Accident Date: 11/07/2021  
 TP Veh Reg No: SHD6277M

*Not Authored*  
*Meromy Repair*  
*3 days*

Estimate No: ES2190688/YISHUN  
 Date: 21 Jul 2021  
 Policy No: 5122116353  
 Veh Reg No: SLP4929T  
 Make/Model: HONDA HONDA HIT 1.3GF CVT  
 Chassis No: GK31343822  
 Engine No: L13B1452135  
 Reg. Date: 21/03/2019

## Estimate Repair Cost to Vehicle No :SLP4929T

Description	U/Price	Quantity	List Price	Amount
			S\$	S\$
<b>List Price</b>				
1 FRONT BUMPER	821.20	1 PC	821.20	✓
2 FRONT BUMPER LH SIDE RETAINER	12.00	1 PC	12.00	✓
3 FRONT BUMPER LH FOG LAMP GARNISH	173.10	1 PC	173.10	?
4 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	✓
			1,027.30	
	Less 20%		205.46	821.84
<b>Special Net</b>				
5 FRONT NUMBER PLATE	30.00	1 PC	30.00	✓
			30.00	30.00
<b>Labour</b>				
6 REMOVE & REFIX FRT BUMPER ASSY,FOG LAMPS,KNOCK & REPAIR FRT RH FENDER INNER PANEL & REALIGN THE SAME	400.00	1 LA	400.00	300
7 PUTTY & RESPRAY ON FRT BUMPER,FRT RH FENDER INNER PANEL,FRT RH FENDER	450.00	1 LA	450.00	400
8 TO APPLY,REMOVE & REFIX OPC SEAL AND SEND VEHICLE FOR INSPECTION (INCLUDING EDAY LICENCE)	80.00	1 LA	80.00	✓
			930.00	930.00
			Total	S\$ 1,781.84
			Add GST @ 7%	124.73
			Total Amount Payable	S\$ 1,906.57

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Cheng Hoe Motor Pte Ltd

*[Signature]*

AUTHORISED SIGNATURE

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission ..... 12/07/2021 08:44 (SGT)  
Date of Accident ..... 11/07/2021 18:57 (SGT)  
Exact Location of Accident ..... Singapore  
Additional Location Information ..... ROUNDABOUT ALONG CHAI CHEE ROAD, NEAR BLOCK 10  
Country/State of Loss ..... Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLP4929T

### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... YAP YI PING  
NRIC No ..... S9028742G  
Email Address ..... JUSTIN\_TAN@MSN.COM  
Mobile Phone No ..... (Phone) +65-98352754  
Alternative Phone No ..... +65-98352754

### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Fit  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car  
Transmission ..... Auto  
CC ..... 1400

### INSURANCE COMPANY

Name of Insurance Company ..... NTUC Income Insurance Co-operative Ltd  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... 5122116353  
Cover Note Number ..... -

### DRIVER

Name of Driver ..... TAN SONG RUI, JUSTIN  
NRIC No ..... S8921280D

 Accident report SN07217C0001

