

ASS. REC. BY: Tanjith

REF:

CC3/CT121007731/T1e93.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHD 18224 Yr Regn: 2029 Nov.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai c.c. 1580

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 95415 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KMHCS81CVLY-212221

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 200

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Hankook

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. _____ D.O.I. 10/8/21 @ 230pm.

Survey held at Premier Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Date/Time, File Pass to?

☐ : Preli. Report

1) _____
Date/Time, File Return to?

☐ : Final Report

2) _____

Report Format: _____

Lump Sum / L&L: _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

10-Aug-21

ESTIMATE REPAIR BILL FOR HYUNDAI IONIQ REGN NO: SHD 1822 Y

1 pc	Front bumper	\$	430.90 <i>Ry</i>
1 pc	Front bumper centre grille cover - Upper	\$	108.50 <i>Ry</i>
1 pc	Front bumper centre grille	\$	708.90 <i>X</i>
1 pc	Front bumper emblem "HYUNDAI"	\$	28.00 <i>19</i>
1 pc	Front bumper strip	\$	29.40 <i>X</i>
1 pc	Radiator Grille	\$	708.90 <i>out</i>
		\$	2,014.60
		Less 20%	\$ 402.92
		\$	1,611.68
S/NETT			
1 pc	Front bumper clips	\$	48.00 <i>X</i>
1 pc	Front number plate with casing	\$	50.00 <i>X</i>
Sundry		\$	50.00 <i>X</i>
To adjust / focus front n/s & o/s head lamps		\$	80.00 <i>X</i>
To check for wiring		\$	50.00 <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same.		\$	550.00 <i>200</i>
To putty and spray painting on front bumper, front centre grille moulding		\$	400.00 <i>200</i>
		\$	3,019.68

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Tanpin 97495749
WP 10/8/21 @ 230pm
P/P Requiring new parts
2 days
Tanpin @ lkhauto.com

Vehicle Registration Details

Vehicle No. SHD1822Y	Make/ Model HYUNDAI/AE IONIQ HEV FL 1.6 DCT	Vehicle Scheme Taxi (Company)
Current Propellant Petrol-Electric	Chassis No. KMHC851CVLU212221	Vehicle Type Public Transport Taxi (Motor Car)

Owner's Details

Owner Name:

PREMIER TAXIS PTE. LTD.

NRIC/Passport/Company Cert No.:

200304975H

Mailing Address:

-

Owner ID Type:

Company

Registered Address

**23 CHANGI SOUTH AVENUE 2 #04-03
SINGAPORE 486443**

Birth Date:

-

Registration Details

Previous Vehicle No.:

-

Effective Date of Ownership:

30 Nov 2020

Original Registration Date:

30 Nov 2020

Registration Date:

30 Nov 2020

No. of Transfers:

0

IU Label No.:

1050552794

Vehicle Specifications

Engine No.:

G4LELU497664

Chassis No.:

KMHC851CVLU212221

Year of Manufacture:

2020

Motor No.:

PM04L1D178DJ

Primary Colour:

Silver

Secondary Colour:

-

Passenger Capacity:

4

Engine Capacity / Power Rating:

1580 cc / 32.0 kW

Maximum Power Output:

103.6 kW (138 bhp)

Max Unladen Weight:

1361 kg

Maximum Laden Weight:

1870 kg

Vehicle Attachment 1:

Alr-Con (Taxi)

Vehicle Attachment 2:

-

Vehicle Attachment 3:

-

Additional Registration Fee (ARF) and COE Information

Open Market Value:

\$25,527.00

Additional Registration Fee Rate:

First \$20,000.00 (100%), next \$5,527.00 (140%)

Actual ARF Paid:

\$12,738.00

Vehicle Lifespan Expiry Date:

29 Nov 2028

OPC Cash Rebate Eligibility:

No

QP during COE Bidding Exercise:

\$0.00

COE No.:

2020113001001942E

COE Expiry Date:

29 Nov 2028

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Registration Category:

A - Car up to 1600cc & 97kW (130bhp)

Quota Premium (QP) / Prevailing Quota Premium:

- / \$36,475.00

PQP Paid

\$29,180.00

QP (Regn Cat):

--

PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

29 Nov 2028

Minimum PARF Benefit:

\$7,642.00

Vehicle Emissions Details

CO2 Emission:

86.00 (g/km)

CO Emission:

0.109280 (g/km)

NOx Emission:

0.002060 (g/km)

Message:

This is a public service vehicle.

CEV/VES Rebate Utilised Amount:

\$15,000.00

HC Emission:

0.028670 (g/km)

PM Emission:

0.052000 (mg/km)

Printed on 30 Nov 2020 10:01:35

Copyright © Land Transport Authority of Singapore 2020