


ASS. REC. BY: Steve 7 CS/AIG 21007749/ELV3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
☒ TP/WS/TPRES/OD-RES/EVA/INV/MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Est. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 G/A / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Cum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLZ 4939L Yr Regn: 7/5/18
 Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or _____
 Make: KIA Forte c.c. 1591
 Colour: Blue A/O: Insured / Std / NI / N
 Sp. Reading: 39848 T/Radio: Insured / Std / NI / N
 Eng/No: _____
 C/No: KNAEJ411M-T3762297
 Gen. Cond: Good / Fair / Poor / Bught
 Steering: Inorder / Jammed / Locked / Burnt or
 Brakes: Inorder / Jammed / Locked / Burnt or
 Mod: NH / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R5
 R: h
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kumho
 Front: _____ Rear: _____
 R/Bal: 4 mm R/Bal: 4 mm
 L/Bal: 4 mm L/Bal: 4 mm
 D.O.A. 16/7/21 D.O.L. 19/7/21
 Survey held at Cycle & Collaps
 Des. of Damages: ☒ Fnt / ☐ Rear / ☐ O/S / ☐ N/S / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time	Action / Instruction
	<u>MV-63K</u>

Time/Time, File, Post log. ☐ : Prel. Report
☐ : Final Report

Time/Time, File Return log?

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$) _____
☐ : Interview (\$) _____
☐ : Tech. Inve (\$) _____
☐ : VV&I and (\$) _____

Survey Fee:

Transportation

Provision

Others

TOTAL



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
Balpreet Kaur Dhillon	Cust No/Name /Balpreet Kaur Dhillon
28 Jalan Gelenggang	Reg No/Reg Date SLZ4939L / 07/05/201
Singapore 578202	Date In/Mileage / 39848
Contact No Mobile: 96696319	Chassis No KNAFJ411MJ5762297
	Engine No G4FGHH692691
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	19/07/2021/ 12:01	BLE	261 / Edwin Caina	36346			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000	1	2	1					2400.00
RENEW FR BUMPER , FR SUPPORT & BONNET								1400
REPAIR LHF FENDER , LHF A PILLAR , RHF FENDER & RHF A PILLAR					3-5	x	410	2100.00
E PNT98000	1	1	1					1400
RESPRAY FR BUMPER , BONNET , LHF FENDER , LHF A PILLAR ,					4	x	359	
RHF FENDER & RHF A PILLAR								100.00
E PNT88000								
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								
TOP UP AC GAS								30.00
A 54900099								
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								120.00
A 10028901								
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								50.00
M SUNDRY								
SUPPLY FR NUMBER PLATE WITH CASING					MJS			40.00
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								40.00
M SUNDRY								
SUPPLY BODY PNL SEALANT								20.00
M SUNDRY								
Sundries					1.00	633.00	00.00	633.00
M COVER-FR BUMPER	BR				1.00	9.00	00.00	9.00
M CAP-FRONT HOOK	X				1.00	18.00	00.00	18.00
M MOULDING-FRT BPR LICENSE PLATE	BR				1.00	55.00	00.00	55.00
M LIP ASSY-FRONT BUMPER	CUT				1.00	160.00	00.00	160.00
M GRILLE ASSY-RADIATOR	MJS				1.00	54.00	00.00	54.00
M GARNISH-RADIATOR GRILLE,UPR	BR				1.00	29.00	00.00	29.00
M STRIP ASSY-FR BUMPER UPR	TN				1.00	91.00	00.00	91.00
M MOULDING-FRONT BUMPER A/INTAKE	?				1.00	6.00	00.00	6.00
M DUCT ASSY-AIR CURTAIN,LH	?				1.00	6.00	00.00	6.00
M DUCT ASSY-AIR CURTAIN,RH	?				1.00	33.00	00.00	33.00
M AIR DUCT-FR BUMPER,LH	?							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
Balpreet Kaur Dhillon	Cust No/Name /Balpreet Kaur Dhillon
28 Jalan Gelenggang	Reg No/Reg Date SLZ4939L / 07/05/201
Singapore 578202	Date In/Mileage / 39848
Contact No Mobile: 96696319	Chassis No KNAFJ411MJ5762297
	Engine No G4FGHH692691
	Make/Model KIA/FORTE K3 1.6 A L 189
	Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00081	Cash	19/07/2021/ 12:01	BLE	261 / Edwin Caina	36346

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M AIR DUCT-FR BUMPER,RH	1.00	33.00	00.00	33.00
M ABSORBER-FRONT BUMPER ENERGY / GR	1.00	84.00	00.00	84.00
M STIFFNER-FR BPR LWR	1.00	114.00	00.00	114.00
M RAIL ASSY-FR BUMPER	1.00	496.00	00.00	496.00
M BRACKET-FR BUMPER SIDE MTG,LH	1.00	13.00	00.00	13.00
M BRACKET-FR BUMPER SIDE MTG,RH	1.00	13.00	00.00	13.00
M PANEL ASSY-HOOD / DO	1.00	1384.00	00.00	1384.00
M HINGE ASSY-HOOD,LH / BT	1.00	34.00	00.00	34.00
M HINGE ASSY-HOOD,RH / BT	1.00	34.00	00.00	34.00
M LATCH ASSY-HOOD	1.00	65.00	00.00	65.00
M LAMP ASSY-HEAD,LH	1.00	810.00	00.00	810.00
M LAMP ASSY-HEAD,RH	1.00	810.00	00.00	810.00
M ORNAMENT-KIA NO.115 / CAT	1.00	32.00	00.00	32.00
M CONDENSER ASSY-COOLER / DO	1.00	681.00	00.00	681.00
M GUARD-AIR,LH	1.00	19.00	00.00	19.00
M GUARD-AIR,RH	1.00	19.00	00.00	19.00
M RADIATOR ASSY	1.00	546.00	00.00	546.00
M FILLER NECK ASSY-RADIATOR	1.00	49.00	00.00	49.00
M BLOWER ASSY	1.00	623.00	00.00	623.00
M SHIELD-AIR INTAKE	1.00	10.00	00.00	10.00
M DUCT-AIR "B"	1.00	77.00	00.00	77.00
M DUCT ASSY-EXTENSION	1.00	144.00	00.00	144.00
M COOLANT (4L)	1.00	26.00	00.00	26.00

Estimate

* from Suppl part - DO SURVEYOR NAME: Steve CLKK 19/7/21, 2:00pm

SURVEYOR SIGNATURE: DO-MH PL

DATE: EX-105-1

REMARKS: P/P, My Bil Sy
7 dys

Confirm & accepted by hence notify

the repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed

Authorized signatory and company stamp

	Nett	12,190.00
7% GST on	12190.00	853.30
Total Payable		13,043.30

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

CTA217H0002 / CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
ENTRY DATE & TIME: 19/07/2021 08:53 (SGT)
SUBMITTED BY: SONGCUAN LAURO JR ARAOS
VERSION: 1 (19/07/2021 08:53 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 19/07/2021 08:53 (SGT)
Date of Accident 16/07/2021 00:28 (SGT)
Exact Location of Accident Marymount Rd, Singapore
Additional Location Information TRAFFIC LIGHT AT THE CROSS JUNCTION OF MARMOUNT RD
..... & SHUNFU RD TOWARDS ANG MO KIO
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLZ4939L

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner BALPREET KAUR DHILLON
NRIC No SXXXX272I
Email Address Balpz_dhillon@yahoo.co.uk
Mobile Phone No (Phone) +65-96696319
Alternative Phone No +65-96696319

VEHICLE PARTICULARS

Manufacturer Kia
Model Forte
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1591

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1800045081-02
Cover Note Number -

DRIVER

PIC No	SXXXX272I
Date Of Birth	27/09/1989
Occupation	Indoor
Date Of Driving Pass	09/09/2009
Driving experience	11 YEARS AND 10 MONTHS
Gender	Female
Mobile Number	(Phone) +65-96696319
Alt. Phone Number	+65-96696319
Email Address	Balp_z_dhillon@yahoo.co.uk
Address	28 JALAN GELENGGANG
Address complement	SINGAPORE
Postcode	578202
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	Yes
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

FOREIGN VEHICLE 1

Vehicle Registration Number	JTE2139
Vehicle Category	Motorcycle

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bishan Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18005529999
Alt. Police Station Phone No	(Fax) +65-65561905
Police Station Address	20 Bishan Street 23 Singapore 579757
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT AND POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
-
Black
Motorcycle
YEOW JUN WEN
(Phone) +65-86112700
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


17/7/21
1125hrs
Policyholder's Signature / Date & Time

NA
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 16 Jul 2021, at 0028hrs, I was driving home from work and stopped at the red traffic lights of Marymount Rd, at the cross junction with Shuntan Rd, heading towards Ang Mo Kio. I spaced out momentarily as I was exhausted. While stopped, a traffic light further down the road turned green, and I accidentally reacted to that, although my traffic light was still red.

As I moved off, I crashed into the back of a black motorcycle stopped in front of me that I had not noticed before. I stopped on impact but by this time, the back wheel of the motorcycle had become stuck under the front of my car.

The rider and his pillion were able to hop off the bike in time, and did not seem to have any obvious injuries. I did not sustain any injuries as well. Traffic Police was called to scene as the motorcycle was Malaysian-registered, and the two vehicles could not be separated from each other. Therefore, the vehicles were also still blocking the road. This was done while awaiting for the tow truck to arrive.

Declaration

We declare the foregoing particulars are true in every respect.

 17/7/21
1125hrs

NA



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



SINGAPORE POLICE FORCE



T/20210716/2056

1 of 4

Report No. T/20210716/2056

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made:
16/07/2021 12:41

Vide Report No.:
E/20210716/0007

Station Diary No.:
54

Informant's Particulars

Name of Informant:
BALPREET KAUR DHILLON

ID Type / ID No.:
NRIC NO / S89332721

Nationality:
SINGAPORE CITIZEN

Sex: Female Age: 31 Date of Birth: 27/09/1989

Race:
Sikh

Occupation:
SAF REGULAR

Address:
28 JALAN GELENGGANG SINGAPORE 578202

Contact No.:
Home/Office: Mobile: 96696319

Email:

Type of Informant:
Driver

Language:

Institution / School Name:

Driving Licence Information:
Class: 3

Date of Expiry:

General Information of the Accident

Type of
Accident:

Non-Injury
Foreign Vehicle

Drink
Drive:
No

Date/Time of
Accident:
16/07/2021 00:25

Type of Location:
X-Junction

Location:

MARYMOUNT ROAD

Weather:
Clear

Road Surface:
Dry

Road Speed Limit:

Traffic Flow:
Dual Carriage Way

Traffic Control:
Traffic Light - Working

Traffic Volume:
Light

Type of Collision:
Between Moving Vehicles - Head To Rear

Anyone conveyed by
ambulance:
No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
JTE2139	Motorcycle				Slightly Damaged	1
SLZ4939L	Car	KIA	FORTE K3 1.6A	Blue	Slightly Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLZ4939L	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1800045081-02	07/05/2021	06/05/2022



SINGAPORE POLICE FORCE



T/20210716/2056

2 of 4

Report No. T/20210716/2056

Police Station Of Origin:
Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757

Tel No: 1800-5529999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No		Use of Pedestrian Crossing: NA	
No. of Pedestrians Injured: NIL			
Name	Yeow Jun Wen	ID No.	G8547005T
Related Vehicle	JTE2139 (Motorcycle)	Contact No.	86112700
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	BALPREET KAUR DHILLON	ID No.	S8933272I
Related Vehicle	SLZ4939L (Car)	Contact No.	96696319
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 16/7/2021 at about 0028hrs, I was driving my vehicle (SLZ4939L) along Marymount Road towards Ang Mo Kio Ave 1 direction. When the traffic light at the cross junction of Marymount road and Shunfu road turned red, I slowed down my vehicle and came to a stop. As I was feeling exhausted, I recalled that I spaced out for a while. I did not notice that the motorcycle (JTE2139) stopped in front of my vehicle (SLZ4939L). Shortly after, I noticed that a traffic light turned green, so I moved off and collided head-to-rear into the motorcycle (JTE2139). I stopped my vehicle upon experiencing the impact of the slight collision. At that point of time, I realised that I had accidentally reacted to the green traffic light ahead of the current traffic light as the current traffic light was still red.

Subsequently, I noticed that the rear wheel of the motorcycle (JTE2139) got stuck under my vehicle front bonnet. Both the rider and pillion of the motorcycle (JTE2139) were able to hop off their motorcycle. However, we were unable to move the vehicles. I did not observe any visible injuries on both the rider and pillion, but they informed that they may be seeking medical consultation after the accident. I also did not sustain any injury. As both the motorcycle (JTE2139) and my vehicle (SLZ4939L) were stuck together, we called for traffic police assistance. The traffic police came to scene and provided me with a case card vide E/2210716/0007, Traffic police IO Wei Li, Contact number 65476394. Lastly, we engaged a towing crew to shift the vehicles away. My vehicle does not have a working in-car CCTV.

After the accident, I observed that my vehicle (SLZ4939L) front bonnet was badly damaged, the vehicle registration plate dislodged, and there was radiation fluid leakage.

I am lodging report as instructed by the traffic police.



**SINGAPORE
POLICE FORCE**



T/20210716/2056

3 of 4

Report No. T/20210716/2056

Police Station Of Origin:
Bishan N.P.C
20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT



SINGAPORE POLICE FORCE



T/20210716/2056

4 of 4

Report No. T/20210716/2056

Police Station Of Origin:
Bishan N.P.C

20 Bishan Street 23 SINGAPORE 579757
Tel No: 1800-5529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 3 LIM LI CHENG

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:

TP / AEIT /

SSI TAY CHUN KEEN

Contact No.: 65476436



Signature Of Informant:

Date/Time:
16/07/2021 12:41

Classification Of Case:

Authentication Stamp
NP168

AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : BALPREET KAUR DHILLON
 Period of Insurance : 07 May 2021 To 06 May 2022
 Engine No. : G4FGHH692691
 Chassis No. : KNAFJ411MJ5762297

Vehicle No. : SLZ4939L
 Policy No. : 1800045081-02
 Endorsement No. :
 Issued Date : 20 Mar 2021

ABOUT THE COVER

Make/Model : KIA FORTE K3 1.6 A EX
 Engine Capacity/Tonnage : 1,591.00 CC
 Driver Restriction : NA
 Person or Classes of Persons Entitled to Drive* :
 at The Policyholder
 at Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.
 You have to pay an additional sum of \$9,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Sum Insured : Market Value
 Off Peak Car : No
 First Year of Registration : 2018
 Insuring with COE/PARF : Yes

Age Condition : All Age Condition
 Limitation as to use* :
 Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.
 Mileage Condition : Unlimited Mileage
 Loss of Use 150000 - 160000
 * Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1937 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings

EXCESS

Section 1
 Fire - \$0 Own Damage - \$500 Theft - \$0 Flood Cover - \$500
 Section 2
 Property Damage - \$0
 Windscreen : \$100
 Named Driver and EXCESS (where applicable)
 BALPREET KAUR DHILLON - \$500 (Own Damage), \$500 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Damage Body & Paint Centre Add: 209 Pandan Gardens Singapore 809339 65684501
 2. Cycle & Damage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
 3. Cycle & Damage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159831 64278800
 4. Cycle & Damage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
 For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6336 6200. Alternatively, you may refer to AIG website www.aig.sg or
 AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: Standard Chartered Bank (Singapore) Limited
 We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1937 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1958 (Malaysia)

05048222236
 CEC/KICPZ - NICHOL
 299 ALEXANDRA ROAD
 SINGAPORE 159830
 Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 This computer generated document does not require a signature.

AIGSMOBILEAPP