

ASS. REC. BY:

REF:

~~CS3/AGI18013456/T1tf3~~

Special Instruction:

Surveyor:

Tau Hieh

ASSIGNMENT (Office)

19/7/2021 5:44 PM

From (Person):

~~Julie Wang~~

of

AGI

Date/Time:

~~24/7/18 @ 12:50pm~~

Estimated Cost:

DARRYL QUEK

Bill to:

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FU353A

Insured:

8KA 8213P

at Workshop m/s:

Chek Kong Motor

Tel:

6769 8793

of

387 B, Yew Tee Ind. Est. Woodlands Rd

Policy No:

C10001787/JM

Claim No:

~~C10001787/JM~~

TWK/pkf/2224/18

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A.

17/07/2018

CA / REV / REP. / REV 24 HRS

up

25/7/18

H.O.D. Endorsement:

Date/Time:

5:06pm @ 24/7/18

Person Contacted:

Kebon

Vehicle IN OUT

Date/Time	Action/Instruction (X) Estimate
	FU 353A - NBA / MSG17622571 / Y
	8KA 8213 P - X

D.O.A: 26/11/2017

DATE/TIME

Tanfki

REF:

AG 1

PKS.

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

[Signature]	
N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lump Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No. F4353A Yr Regn: _____

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Deus C.C. _____

Colour: 4/1 Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 41258 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JA200 000 3667

Gen. Cond: 3 / Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 90/90 R17

R: 170/90 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 25/3/18 2.37pm

Survey held at Chek Kong

Des. of Damages Frnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision:

Date / Time Action / Instruction BLK. 1 587RS Jaws to Ind East

No GIA.
Estimated repair range \$6,000 - \$7,000 Range + No. of days.
1/8 Submit PRS report.
[Signature]
1/8/18

Date/Time, File Pass to? : Preli. Report : Final Report

1) _____

Date/Time, File Return to? _____

2) _____

Report Format: PRS

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: -

Survey Fee: _____

Transportation: _____

(\$ _____)

Add Fee: Site Insp (\$ _____) Photos

Interview (\$ _____) Others

Tech Invs (\$ _____)

Weekend (\$ _____)

TOTAL _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL		Ref : CS3/AGI18013456/T1z4d3	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date : 24-07-2018	
		Code : AGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKA 8213P	Veh. Inspected	FU 353A
Policy No.		Coverage (\$)	0.00
Claim No.	C10001787/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	24/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	17/07/2018	Inspection Date	25/07/2018
Survey held at	CHEK KONG MOTOR 387B YEW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			

Nivitha (LKK Auto)

From: Julie Mangubat <julie.m@budgetdirect.com.sg>
Sent: Tuesday, 24 July 2018 12:50 PM
To: sur@lkkauto.com; ASSIGNMENTS@LKKAUTO.COM
Subject: Our ref: C10001787/JM || Your ref:
Attachments: FAX_20180724_1532395498_23.pdf

Hi Team

Please accept PRI on without prejudice basis.

Thank you,
-Julie

From: eFax <message@inbound.efax.com>
Sent: Tuesday, 24 July 2018 9:25 AM
To: Elvina Lim <elvina.lim@budgetdirect.com.sg>; Customer Care <help@budgetdirect.com.sg>; Rose Liau <rose.liau@budgetdirect.com.sg>
Subject: eFax message from "unknown" - 4 page(s), Caller-ID: UNAVAILABLE



Hello Customer,

You have a new fax! Click the attachment to view.

You can also view your faxes in the eFax mobile app or by [logging in to your account online](#).

Fax Details

Caller ID: UNAVAILABLE
Date Received: 2018-07-24 09:24:58 SGT
Type: Attached in pdf
Number of pages: 4
Reference #: sin1_did12-1532395388-67250611-23

If you have any questions, please visit our contact [Customer Support](#).


Thank you for choosing eFax!

Sincerely,
The eFax Team

Download the App:




Follow us:



© 2018 j2 Global, Inc. and affiliates. All rights reserved.
eFax is a registered trademark of j2 Global, Inc. and affiliates.

This account is subject to the terms listed in the [eFax Customer Agreement](#).



This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.



GOH JP & WONG, LLC

advocates & solicitors
commissioner for oaths

GOH TECK WEI

WONG TZE HOY

WONG FUNG KWAI

SOON WEI SONG

133 New Bridge Road #16-09 Chinatown Point Singapore 059413

Tel: 6538 5868 Fax: 6538 4898 (Not for service of Court documents) Email: mail@gohjpwong.com

Goh JP & Wong LLC is a law corporation with limited liability. GST/UEN: 201406078M

YOUR REF:

OUR REF:

GTW.ACC.7110.18.dn

WHEN REPLYING, PLEASE QUOTE OUR REFERENCE NO

DATE:

23rd July 2018

Tan Chin Hee
8 The Inglewood
Singapore 575037

Dear Sirs

NOTIFICATION OF ACCIDENT

**SUBJECT MATTER: TRAFFIC ACCIDENT INVOLVING FU 353A & SKA 8213P ON 17.07.2018
AT JUNCTION OF HAVELOCK ROAD AND OUTRAM ROAD**

We act for Muhammad Harris Bin Amin in the above matter.

We are instructed to notify you of the above accident on 17th July 2018 at about 5:30 pm at junction of Havelock Road and Outram Road involving our client's motorcycle FU 353A and motorcar SKA 8213P driven by you at the material time. A copy of our client's traffic police report filed is enclosed.

As a result of the accident, our client's motorcycle FU 353A has been damaged. Before our client proceed to repair the damaged vehicle, please let us know within 2 working days (excluding Saturdays, Sundays and Public Holidays) of your receipt of this notice whether you or your insurer would like to conduct a pre-repair inspection of the vehicle or whether you or your insurer waive the pre-repair inspection. If we do not receive any reply from you within the stipulated timeline our client shall proceed to repair the vehicle without further reference to you.

Yours faithfully

Goh Teck Wei

Enc.

Cc **Auto & General Insurance (Singapore) Pte Ltd**
Singapore
Attention: Motor Claims Department

BY FAX ONLY
Fax No. 6725 0611

Cc **Chek Kong Motor Pte Ltd**
Fax No. 6769 7367
Please do not proceed with repairs until further notice.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

PRE-REPAIR INSPECTION REPORT			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE)190 CLEMENCEAU AVE #03-01SINGAPORE SHOPPING CTR S239924		Ref: CS3/AGI18013456/T1z4d3s2 Date: 02-08-2018 Code: AGI	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKA 8213P	Veh. Inspected	FU 353A
Policy No.		Coverage (\$)	0.00
Claim No.	C10001787/JM	Excess (\$)	0.00
Assign From	JULIE MANGUBAT	Assign Date	24/07/2018
2. Vehicle Particulars & Condition			
Make & Model	DEUS	c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	TA2000003667	Colour	BRONZE
Odometer	46258 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	90/90 R17	PIRELLI	5 mm
L/H Front Tyre			mm
R/H Rear Tyre	130/90 R15	PIRELLI	5 mm
L/H Rear Tyre			mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND N/S BODY.			
5. General Information			
Accident Date	17/07/2018	Inspect Date / Time	25/07/2018 (02:37 PM)
Survey held at	CHEK KONG MOTOR 387B YEOW YEE INDUSTRIAL ESTATE WOODLANDS ROAD SINGAPORE 677948		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D)THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$6,000-\$7,000			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR		5 Working Days	

Report Ref No. CS3/AGI18013456/T1z4d3s2

Inspected By

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.