



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 21/07/2021	Cust No/Name	/EUGENE SEAH WEE JIN (EUGENE SHE
	Reg No/Reg Date	SDH9923M*KC17/ 28/06/2019
	Date In/Mileage	21/07/2021/ 16560
	Chassis/Package	KNAF3416MK5049704 /#
	Engine No	G4FGKH744163
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No					
LAX00000	Credit	05/08/2021/ 14:34	BLE	260 / AiTing	36434					
Description of Goods / Services					Qty	Unit Price	Disc%	Amount		
E	PNT88000	REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT LID, REAR END PANEL, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 1400.00
E	PNT98000	RESPRAY ON REAR BUMPER, REAR END PANEL, BOOT LID, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 1440.00
E	PNT88000	REMOVE & REINSTALL BOOT LID COMPONENTS TO NEW PANEL								✓ 120.00
E	PNT88000	REMOVE & REINSTALL REAR FLOOR BOARD, TRIMS & CARPET, TO FACILITATE REPAIR								? 120.00
A	54900099	CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A	10028901	CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
E	PNT88000	REMOVE & REINSTALL REVERSE SENSOR TO FACILITATE REPAIR								✓ 80.00
M	SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS								✓ 40.00
M	SUNDRY	SUPPLY BODY PANEL SEALANT								✓ 40.00
M	SUNDRY	SUPPLY C&C BADGE								✓ 40.00
M	SUNDRY	SUNDRIES								✓ 20.00
X	COVER-RR BUMPER					1.00	✓ 651.00	20.00	520.80	
X	COVER-RR BUMPER LWR					1.00	✓ 241.00	20.00	192.80	
X	COVER-RR BUMPER FOG LAMP,LH					1.00	✓ 88.00	20.00	70.40	
X	BEAM-RR BUMPER					1.00	✓ 318.00	20.00	254.40	
X	STAY-RR BUMPER LH					1.00	? 65.00	20.00	52.00	
X	STAY-RR BUMPER RH					1.00	? 65.00	20.00	52.00	
X	BRACKET-RR BEAM LWR,CTR					1.00	✓ 6.00	20.00	4.80	

This is not an official tax invoice.
This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 21/07/2021	Cust No/Name	/EUGENE SEAH WEE JIN (EUGENE SHE
	Reg No/Reg Date	SDH9923M*KC17/ 28/06/2019
	Date In/Mileage	21/07/2021/ 16560
	Chassis/Package	KNAF3416MK5049704 /#
	Engine No	G4FGKH744163
	Make/Model	KIA/CERATO 1.6 A SX SR G518
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/08/2021/ 14:34	BLE	260 / AiTing	36434			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
X	BRACKET-RR BEAM LWR MTG			(1)	2.00	✓ 6.00	20.00	9.60
X	CLIP				10.00	✓ 1.00	20.00	8.00
X	PANEL ASSY-TRUNK LID				1.00	✓ 1297.00	20.00	1037.60
X	PANEL ASSY-BACK				1.00	✓ 324.00	20.00	259.20
X	TRIM ASSY-RR TRANSVERSE				1.00	✓ 41.00	20.00	32.80
X	W/STRIP-TRUNK LID OPNG				1.00	✓ 100.00	20.00	80.00
X	LOGO ASSY-KIA SUB				1.00	✓ 32.00	20.00	25.60
X	EMBLEM-CERATO				1.00	✓ 28.00	20.00	22.40
Z	TEXT							
	AIG OD CLAIM.							
	DOA : 21.07.21							
	SURVEYOR STEVE LKK 21.07.21							
	POLICY NO: 1900114470-01, REPAIR 07 DAYS							
Pro Forma								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Pro Forma

Parts	2,622.40	Nett	6,072.40
Labour	3,310.00	7% GST on	6072.40
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	140.00		
Total(w/o GST)	6,072.40	Total Payable	6,497.47

This is not an official tax invoice.
This is a computer generated document, no signature is required.

WIP: 36434 (ADDITIONAL PARTS CHANGE)

CAR NO: SDH9923M

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	stay - RR Bumper LH	? / SUPP		/ CR# 07	
2	stay - RR Bumper RH	? / SUPP		/ CR# 07	
3	Bracket - RR Beam CTR	? / SUPP		/ CR#	
4	Bracket - RR Beam mtg X2	? / SUPP		/ CR#	
5	Trim assy - RR Transverse	? / SUPP		/ CR#	
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
28/7	Fja
PHOTO BEFORE PAINT	
PHOTO AFTER PAINT	
PHOTO OF MOUNT TO CELLETTE BENCH	
REMOVE AND INSTALL ENGINE	
REMOVE AND INSTALL DASHBAORD	
REMOVE & INSTALL FUEL TANK	
PHOTO UNDERCARRIAGE PARTS	

MODEL: CERATO

SURVEYOR: STEVE



HOME

Online



CERATO/FORTE../2019/G 1.6 MPI..

VCI



Fault Code Searching

Rescan

Clear All DTC

Go to DTC

Save



12/12

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good
EPS	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.

M-E-K-01-00-0251

VCI Ver.

02.59

ECU Ver.

M-E-K-01-00-0192

OS Ver.

Android 10