ASS. REC, BY: Marcus REF: CS/ICS	LONGENT TO THE STATE OF THE STA
ASS	IGNMENT  VOLUMENT  VOLUMEN
From: Date:	Vell No.
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP/I WS / TP RES / OD RES / EVA / INV / MV	Truck/Trailer or
To Inspect Vehicle No:	Make: Seat lean JORI-2 c.c 1197
at Workshop m/s	Colour Shie A/C: Insured / Std / NI / NA
of 0.750	Sp.Reading / 6865/ T/Radio: Insured / Std / NI / NA
Insured: SJU 2933R	Eng/No:
Policy No.	C/NO: VSSZZZSFZGR222033
Claims No. DMPC2100232H/02/CT	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
· ·	Tyre Size: F:
(Policy Condition)	R: 205-/57-216
Remark: The veh had commenced its N/S O/S	BS / DUN EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: #\$\int \subseteq \text{L.}	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Balmm R/Balmm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. O mm
Est. Repairs: days Res.: Yes or No	D.O.A. 12/7/2/ D.O.I. 2/. /7/2/
Lum Sum: % 3 Val.: Yes or No	Survey held at
CA / REV / REP. / 24 HRS 7 53 +	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT	
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	/
56 corner No 2016 water	774.
22/07/21@4.55pm Informed Crystabelle	776 <i>∕</i> Tan, we are pending for estimate from repaire
	,
1	
Date/Time, File Pass to? : Preli. Report	Days Of Repair:
1) : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fe	ee: : Site Insp (\$ )s+Rs,si
	:Interview (\$ ) Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$	: Weekend (\$

TOTAL

## ➤ Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

wner ID Type:	Singapore NIDIC
Owner ID:	Singapore NRIC
Vehicle Details	783Z
Vehicle Details	SLJ7646X
Vehicle to be Exported:	No.
ntended Deregistration Date:	19 Jul 2021
Vehicle Make:	SEAT
Vehicle Model:	LEON 5DR 1.2 TSI 110 STYLE 7AT
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	CYV438625
Chassis No.:	VSSZZZ5FZGR222033
Maximum Power Output:	81.0 kW (108 bhp)
Open Market Value:	\$19,581.00
Original Registration Date:	24 Dec 2016
First Registration Date:	24 Dec 2016
Fransfer Count:	0
Actual ARF Paid: Intended PARF Rebate Details	\$9,581.00 47 90
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2026
PARF Rebate Amount: Intended COE Rebate Details	\$7,185.00
COE Expiry Date:	23 Dec 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$48,000.00
COE Rebate Amount:	\$26,051.00
Total Rebate Amount:	\$33,236.00

The information contained herein is correct as at 19 Jul 2021

OK

19-Jul-21

