

100/11/13) wef
ASS. REC. BY: Paul

REF:

CS/CT/21007802/Ritz

2265

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGN 1012C

at Workshop m/s CYCLE & CARRIAGE

of 209, PANDAN GARDEN

Insured: CTI

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: 68K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGN 1012C Yr Regn: 2016 / 86P

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA CARENS 1.7(A) S/R c.c. 1685

Colour: GREY A/C: Insured / Std / NI / NA

Sp. Reading: 119102 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KNAPHU 815VH7164359

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 18/07/21

D.O.I. 27/08/21

Survey held at CYCLE & CARRIAGE (PG)

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction

Repair 1.7 - 23K

Finalised amount of \$ 3,782 before GST / 4 days of repair is confirmed

RED: 3604.00 ; 48%

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

☐ S + RS ☐ SI

Photos

Others

Report Format :

Lump Sum / I.B.I. (\$ _____)



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Ms Quek Hui Min (guo Huimin)	Cust No/Name	/Ms Quek Hui Min (guo Huimin)
BLK 115 BUKIT BATOK WEST AVE 6	Reg No/Reg Date	SGN1012C / 15/09/201
#23-200	Date In/Mileage	/ 0
SINGAPORE 650115	Chassis No	KNAHU815VG7164359
Contact No Mobile: 97631012	Engine No	D4FDGH113171
	Make/Model	KIA/CARENS 1.7 A D SX SUNROOF GP8
	Colour/Trim	IM TITANIUM SILVER/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CTP00080	Cash	19/07/2021/ 18:15	TLE	261 / Edwin Caina	36396	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER & RR BUMPER BODY KIT REPAIR RR END PNL & TAILGATE					2560.00 1280
E PNT98000	RESPRAY RR BUMPER , RR END PNL , TAILGATE & RR BUMPER BODY KIT					1100 2200.00
E PNT88000	REMOVE & REFIT RR FLR BOARD , TRIM & CARPET					300.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM					30 50.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM					280.00
E PNT88000	REMOVE & REFIT REVERSE SENSOR					80 100.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS					60 80.00
M SUNDRY	SUPPLY C&C BADGE					50.00
M SUNDRY	Sundries					50.00
M COVER-RR BUMPER,UPR				1.00	576.00 00.00	576.00
M COVER-RR BUMPER LWR				1.00	211.00 00.00	211.00
M BEAM-RR BUMPER				1.00	367.00 00.00	367.00
M BRACKET ASSY-RR BUMPER SIDE,LH				1.00	25.00 00.00	25.00
M HOLDER-BACK WARING SYSTEM OTR				4.00	4.00 00.00	16.00
M ULTRASONIC SENSOR ASSY-P.A.S				2.00	162.00 00.00	324.00
M HOLDER-BACK WARING SYSTEM INR				4.00	4.00 00.00	16.00
M LAMP ASSY-REAR FOG,LH				1.00	116.00 00.00	116.00
M EMBLEM-CARENS				1.00	36.00 00.00	36.00
M EMBLEM-CRDI				1.00	29.00 00.00	29.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: Rashid - Hy 90010066

SURVEYOR SIGNATURE: [Signature]

26/07/2021 @ 1220

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Rashid - Hy 90010066SURVEYOR SIGNATURE: [Signature]DATE: 27/08/21 @ 1220

Confirm & accepted by

REMARKS: 4 daysResy before part

7% GST on

Nett
7386.007,386.00
517.02

Total Payable

7,903.02

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/07/2021 12:11 (SGT)
Date of Accident	18/07/2021 10:25 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	ALONG JURONG EAST CENTRAL TURNING OUT TOWARDS JURONG TOWN HALL ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGN1012C
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	QUEK HUI MIN
NRIC No	SXXXX226J
Email Address	ZEROHOUR1012@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97631012
Alternative Phone No	(Home) +65-97631012

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Carens
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Manual
CC	1700

INSURANCE COMPANY

Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	D300354414QMY
Cover Note Number	-

DRIVER

Name of Driver	QUEK HUI MIN
----------------	--------------

No
Date Of Birth
Occupation
Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

SXXXX226J
10/12/1978
Indoor
22/01/2001
20 YEARS AND 6 MONTHS
Female
(Phone) +65-97631012
(Home) +65-97631012
ZEROHOUR1012@HOTMAIL.COM
39G WEST COAST PARK
#10-23
127718
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
4
No

PASSENGER 1

Name
Gender

ETHAN LEONG
Male

PASSENGER 2

Name
Gender

SUBAEDAH
Female

PASSENGER 3

Name
Gender

ESTELLE LEONG
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

SKETCH PLAN

IMPORTANT NOTICE

- Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel

Sketch Plan




Describe Circumstances of the Accident

- Around 10.25 am on 18 July 2021, I was driving along Jurong East Central.
2. My car was stationary at Jurong East Central junction with Jurong Town Hall Road, waiting to turn out onto Jurong Town Hall Road when there were no cars.
3. Nissan SL5 9664H hit my car from behind.
- Driver - Chang Cheow Siang
- Driver license - S03092421
4. My bumper is dented.


Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date &
Time

19/7/2021

Driver's Signature (If driver is not the policyholder) / Date
& Time


Witnessed by Reporting Centre
Personnel

Kia Carens Diesel 1.7A SX Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map

Price **\$67,800**

Depreciation ⓘ \$11,580 /yr
[View models with similar depre](#)

Reg Date 17-Aug-2016
(4yrs 11mths 18days COE left)

Mileage 82,000 km (16.3k /yr)

Manufactured ⓘ 2016

Road Tax ⓘ \$1,318 /yr

Transmission Auto

Dereg Value ⓘ \$43,176 as of today (change)

Fuel Type Diesel
(Euro 5 Engine and Above)

COE ⓘ \$57,903

OMV ⓘ \$23,995

Engine Cap 1,685 cc

ARF ⓘ \$20,593

Curb Weight ⓘ 1,525 kg

Power 104.0 kW (139 bhp)

Type of Vehicle **MPV**

No. of Owners ⓘ 1

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	226J
Vehicle No.:	SGN1012C
Vehicle to be Exported:	No
Intended Deregistration Date:	29 Aug 2021
Vehicle Make:	KIA
Vehicle Model:	CARENS 1.7(A) DIESEL SUNROOF
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	D4FDGH113171
Chassis No.:	KNAHU815VG7164359
Maximum Power Output:	104.0 kW (139 bhp)
Open Market Value:	\$23,983.00
Original Registration Date:	15 Sep 2016
First Registration Date:	15 Sep 2016
Transfer Count:	0
Actual ARF Paid:	\$20,577.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2026
PARF Rebate Amount:	\$15,432.00
COE Expiry Date:	14 Sep 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$28,753.00
Total Rebate Amount:	\$44,185.00

The information contained herein is correct as at 29 Aug 2021

OK