



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL C/O KELVIN CHIA PARTNERSHIP 6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC TOWER FOUR SINGAPORE 038986		Ref: CS/LAW21007810/Avf3e2 Date: 26/08/2021 Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)</b>			
Insured Veh.	SJS 6779D	Veh. Inspected	SKG 7258K
Policy No.		Coverage (\$)	0.00
Claim No.	SS/sm/2021000427.sompo	Excess (\$)	0.00
Assign From	ANIL	Assign Date	21/07/2021
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	NISSAN ELGRAND	c.c	2488
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	JN1TBAE52Z0800028	Colour	BLACK
Odometer	317285 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	235/55 R18	PIRELLI	6 mm
L/H Front Tyre	235/55 R18	PIRELLI	6 mm
R/H Rear Tyre	235/55 R18	PIRELLI	6 mm
L/H Rear Tyre	235/55 R18	PIRELLI	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	06/01/2020	Inspection Date	02/08/2021
Survey held at	JD MOTORSPORTS PTE LTD 25 KAKI BUKIT ROAD 4 #06-38 SYNERGY @ KB SINGAPORE 417800		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	