ASS. REC. BY:

REF: CS/LAW21007810/Avf3

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SJS 6779D

Policy No. SS/sm/2021000427.sompo

Claims No. TCL.MH.an.50017.20.jdm

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKG 7258K Yr Regn: 2012, Sept.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Nissan Elgrand c.c 2488.

Colour Black. A/C: Insured / Std / NI / NA

Sp.Reading 317285 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JN1TBAE52Z0800028.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/55R18.

R: 235/55R18.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm

D.O.A. 6/1/20 D.O.I. 02/08/21.

Survey held at JD Motorsport.

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP + SJE TP Sompo Reinspection.
25/8/21	LS $3500 (Red 2900,45%)
	MV :
	PV :
	Nett :
	854J.

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2) 25/8/21-Typist

☐ : Preli. Report

☐ : Final Report

Days Of Repair: 4

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Invs ($)

☐ : Weekend ($)

Report Format : TP RES

Lump Sum / I.E.I: ($)

Survey Fee:

Transportation: ___S + RS___SI

Photos

Others

50/50