

# SINGAPORE ACCIDENT STATEMENT

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## ACCIDENT STATEMENT

Date of Submission	16/07/2021 09:33 (SGT)
Date of Accident	16/07/2021 06:05 (SGT)
Exact Location of Accident	Bedok Central, Singapore
Additional Location Information	BEDOK CENTRAL // BEDOK NORTH AVE 3
Country/State of Loss	Singapore

## DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC6381A
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Company Reg No	2XXXXX975H
Email Address	CLAIMS@PREMIERTAXI.COM
Mobile Phone No	(Phone) +65-91550072
Alternative Phone No	(Office) +65-62148880

### VEHICLE PARTICULARS

Manufacturer	Kia
Model	Optima
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1700

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	5107202885-02
Cover Note Number	-

### DRIVER

Name of Driver	YEN SEN FATT
NRIC No	SXXXX258G

Date Of Birth	16/12/1966
Occupation	Outdoor
Date Of Driving Pass	02/10/1996
Driving experience	24 YEARS AND 9 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96585249
Alt. Phone Number	-
Email Address	CLAIMS@PREMIERTAXI.COM
Address	BLK 156 #11-334
Address complement	SIMEI ROAD
Postcode	520156
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	PAX IN THE REAR SEAT - CHINESE (FROM TADA CALL)
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACH

VEH. A - 1 PAX  
VEH. B - NO PAX

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLS2506C
Vehicle Manufacturer	Mazda
Vehicle Model	-

Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private hire
Name of Driver	MALE CHINESE
Contact Number	(Phone) +65-97355308
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



*[Signature]* 517842584

16 JUL 2021

*[Signature]*


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

Sketch Plan

← BEDOC NORTH AVE 3



Describe Circumstances of the Accident

Refer to attached.			
			

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

 517842586

Driver's Signature (if driver is not the policyholder) / Date & Time

16 JUL 2021



Witnessed by Reporting Centre Personnel

Describe Circumstances of the Accident.

ON 16/07/2021 @ 06:05 HRS, I WAS DRIVING MY TAXI ( SHC 6381 A ) TRAVELLING ALONG BEDOK CENTRAL INTO BEDOK NORTH AVE 3 - ON THE LEFT LANE, WITH A PASSENGER ONBOARD.

I SLOWED DOWN MY TAXI TO A COMPLETE STOP - GIVING WAY TO ONCOMING VEHICLES FROM THE RIGHT.

WHILE STATIONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.


WHEN INSPECTED, I DISCOVERED THAT VEHICLE B ( SLS 2506 C - MAZDA ) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR PORTION & VEHICLE B HAD DAMAGES ON THE FRONT PORTION.


NO INJURY INVOLVED. NO AMBULANCE AT SCENE. NO PASSENGERS ONBOARD VEHICLE B.

\*VIDEO FOOTAGE CAPTURED.

DAMAGES FOUND ON VEHICLE A & VEHICLE B



PREMIER TAXI



THIRD PARTY VEHICLE



S1784258G  
SHC 6381A

Driver's Signature & NRIC Number  
Friday, July 16, 2021 @ 9:24:20 AM

( attended by  )