

ASS. FRY:

REF: CS/CTI 21007822/DVC

ASSIGNMENT

From: _____ Date: _____

Estimate Cost: _____

OD / TP / RES / TP RES / OD RES / EVA / RV / MV

To Insp Vehicle No: _____

at Work m/s _____

of _____

Insured _____

Policy # _____

Claim # _____

Sum Insured: _____

Excess: _____

(Check Record)

Make of Ver: _____

(Police Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repair: _____

4

days

Res.: Yes or No

Lima Sum: _____

20

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: _____

SMF 6929X

Yr Regn: _____

Feb / 2020

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: _____

Seat Leon

C.D.

1395

Colour _____

White

A/C:

Insured / Std / RI / NA

Sp. Reading _____

15366

T/Radio:

Insured / Std / RI / NA

Eng/No: _____

CZE 852303

C/No: _____

VSS 2225FZKRO98245

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: _____

F:

225/40 R18

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Goodyear

Front _____

Rear _____

R/Bal. _____

S

mm

R/Bal. _____

S

mm

L/Bal. _____

S

mm

L/Bal. _____

S

mm

D.O.A. _____

20/07/2021

D.O.L. _____

22/07/2021

Survey held at _____

JWG AMK

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

China Taipei SLF 2520D

14/12/2021. Repair 2/3 7,500/- -> 4 days 2/3

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: _____



: Site Insp (\$



: Interview (\$



: Tech Insp (\$

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Photos _____

Repeat Formset: _____

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 137A

Vehicle Details

Vehicle No.: SMF6929X
Vehicle to be Exported: Yes
Intended Deregistration Date: 21 Jul 2021
Vehicle Make: SEAT
Vehicle Model: LEON 5DR 1.4 TSI 150 FR 7AT
Primary Colour: White
Manufacturing Year: 2019
Engine No.: CZE852303
Chassis No.: VSSZZZ5FZKR098245
Maximum Power Output: 110.0 kW (147 bhp)
Open Market Value: \$20,524.00
Original Registration Date: 28 Feb 2020
First Registration Date: 28 Feb 2020
Transfer Count: 0
Actual ARF Paid: \$20,734.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 27 Feb 2030
PARF Rebate Amount: \$15,550.00

Intended COE Rebate Details

COE Expiry Date: 27 Feb 2030
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$32,889.00
COE Rebate Amount: \$26,311.00
Total Rebate Amount: \$41,861.00

The information contained herein is correct as at 21 Jul 2021

OK

Need Items for Your Car?

We have thousands of car parts & accessories to explore.

The best online platform to sell and buy car parts & accessories - Marketplace

Post an Advertisement

Sell it yourself! Advertise it at just

\$68 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Altis 5 Year COE Renewal.



2.88% P.A. by GV CARS
FINANCING PTE LTD. \$0 Down
Available: 2 Years Warranty
GV Credit Pte Ltd. Standard



Browse by Category

Sort by Date Posted

20 results/page

1 vehicles

SEAT Leon

Advanced Search



Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	SEAT Leon	Any	Any	2020	Any	Any	Any	Available
	SEAT Leon CUPRA 2.0A TSI DSG	\$165,800	\$15,930 /yr	24-Nov-2020	1,984 cc	11,800 km	Sports	Available
Facelifted Version. Fully Stock Condition And Never Tracked. 5 Years Ongoing Warranty & Service Package With Agent. Showroom Condition And No Mishaps Ever. High Loan Can Be Arranged. Consignment Agents Please Do Not Call Or WhatsApp. Contact Me To Disc...								
Posted: 18-Jun-2021 Tags: 2020 SEAT Leon, SEAT Leon, SEAT, Leon								

DIRECT OWNER

Save this search criteria, to get email alerts whenever a match is found.

For old advertisements, view Expired ads

20 results/page

Follow sgCarMart.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	21/07/2021 11:48 (SGT)
Date of Accident	20/07/2021 10:45 (SGT)
Exact Location of Accident	Simei Street 1, Singapore
Additional Location Information	JUNCTION OF SIMEI ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF6929X
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	KARL TAY LIQUAN (ZHEN LIQUAN)
NRIC No	SXXXX137A
Email Address	ltkarl25@hotmail.com
Mobile Phone No	(Phone) +65-82019177
Alternative Phone No	+65-82019177

VEHICLE PARTICULARS

Manufacturer	Seat
Model	Leon
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1395

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DMPCSNW00041102100
Cover Note Number	-

DRIVER

Name of Driver	KARL TAY LIQUAN (ZHEN LIQUAN)
NRIC No	SXXXX137A

Date Of Birth	25/10/1989
Occupation	Indoor
Date Of Driving Pass	14/06/2010
Driving experience	11 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-82019177
Alt. Phone Number	+65-82019177
Email Address	ltkari25@hotmail.com
Address	108 SIMEI STREET 1 #11-750
Address complement	-
Postcode	520108
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bedok Division Headquarters
Police Station Phone No	(Phone) +65-18002440000
Alt. Police Station Phone No	(Fax) +65-64443009
Police Station Address	30 Bedok North Road Singapore 469676
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO POLICE REPORT G/20210720/7035

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLF2520D
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	KARL TAY LIQUAN (ZHEN LIQUAN)
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	SLIGHT INJURY
Injured person in which vehicle?	SMF6929X
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Veh A - SMF6929X
Veh B - SLF2520D

Refer to Police Report : A/20210720/7035

I/We declare the foregoing particulars are true in every respect.



21/6/80

Witnessed by Reporting Centre
Personnel


**SINGAPORE
POLICE FORCE**


G/20210720/7035

1 of 2

POLICE REPORT (NP299)

Report No. G/20210720/7035

Police Station Of Origin
Bedok Division HQ
30 Bedok North Road SINGAPORE 469676
Tel No:1800-2440000

Date/Time Report Made 20/07/2021 17:04	Vide Report No.	Station Diary No.
Name Of Informant KARL TAY LIQUAN	Address 108 SIMEI STREET 1 #11-750 SINGAPORE 520108	
ID Type / ID No. NRIC NO / S8938137A	Contact No. Home/Office:	Mobile: 82019177
Nationality SINGAPORE CITIZEN	Email Address LTKARL25@GMAIL.COM	
Occupation Public servant	Sex Male	Age 31
Institution/School Name	Date of Birth 25/10/1989	Race Chinese
	Language English	
Date/Time Of Incident 20/07/2021 10:45	Location Of Incident SIMEI STREET 1	

Brief details.

On the above mentioned date and time, I was driving my vehicle SMF6929X along Simei Street 1 towards Simei Road.

At the junction of Simei street 1 and Simei Road, there was a vehicle in front of me making a left turn.

I followed suit travelling behind said vehicle when suddenly a massive impact from the rear propelled by vehicle forward.

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 20/07/2021 17:04
Officer In-Charge Of Case:	Classification Of Case:
Authentication Stamp	



SINGAPORE
POLICE FORCE



G/20210720/7035

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20210720/7035

My body lunged forward as a result and my left knee knocked against the centre console.

I alighted to realise that SLF2520D had crashed into my vehicle's rear.

Initially, only my left knee felt pain. However, a couple of hours later, my neck, shoulders and lower back areas started feeling stiff and sore.

I went to a nearby clinic, Intemedical Kovan, from where I was at that time as the pain got pretty bad, to seek treatment.

I was given 5 days MC.

Signature Of Officer Recording The Report:

Not applicable

Signature Of Interpreter:

Not applicable

Officer In-Charge Of Case:

Authentication Stamp

Signature Of Informant:

The identity of the person making this report has been authenticated by Singpass. No signature is required.

Date/Time:

20/07/2021 17:04

Classification Of Case:

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SLF2520D [YOUR INSURED] & SMF6929X [OUR CLIENT]
ON 20/07/2021.

ESTIMATED REPAIR COSTS FOR SMF6929X

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Dental</i> 2218.30	\$ 3,142.00	✓
1PC	TAILGATE WINDSCREEN MOULDING <i>Hec</i>	\$ 374.00	✓
1PC	TAILGATE LOGO <i>HH</i>	\$ 134.00	X
1PC	TAILGATE 'LEON' EMBLEM <i>Hec</i> 90.00	\$ 150.00	✓
1PC	TAILGATE 'FR' EMBLEM <i>Hec</i>	\$ 101.00	✓
2PCS	TAILGATE LAMP LH / RH @ \$1,092.00 EACH <i>monrly crack</i> →	\$ 2,184.00	✓ 1378.60
1PC	TAILGATE LOCK <i>Dome</i> 689.30 x 2	\$ 375.00	✓
1PC	TAILGATE SWITCH <i>Dome</i>	\$ 321.00	✓
1PC	TAILGATE INNER TRIM BOARD <i>monrly crack</i> 611.30	\$ 980.00	✓
1PC	TAILGATE WEATHER STRIP <i>svc</i>	\$ 381.00	X
2PCS	TAILGATE HINGE LH / RH @ \$129.00 EACH <i>HH</i>	\$ 258.00	X
2PCS	TAILGATE DAMPER LH / RH @ \$748.00 EACH <i>HH</i>	\$ 1,496.00	X
2PCS	TAIL LAMP LH / RH @ \$1,810.00 EACH <i>HH</i>	\$ 3,620.00	X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$184.00 EACH <i>HH</i>	\$ 368.00	X
1PC	REAR BUMPER <i>distorted / monrly crack</i> 1620.00	\$ 2,290.00	✓
2PCS	REAR BUMPER SIDE RETAINER LH / RH @ \$175.00 EACH <i>HH</i>	\$ 350.00	X
1PC	REAR BUMPER CENTER GARNISH <i>cut / scratched</i> 633.00	\$ 983.00	✓
2PCS	REAR BUMPER NO. PLATE LAMP LH / RH @ \$92.00 EACH <i>HH</i>	\$ 184.00	X 370.00
4PCS	REAR BUMPER SENSOR @ \$321.00 EACH <i>2pc Dome 2pc HH</i> →	\$ 1,284.00	✓
4PCS	REAR BUMPER SENSOR HOLDER @ \$20.10 EACH <i>3x 185.00 x 2</i>	\$ 80.40	X
1PC	REAR BUMPER SENSOR WIREHARNES <i>HH</i>	\$ 3,294.00	X
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$129.00 EACH <i>HH</i>	\$ 258.00	X
1PC	REAR BUMPER LOWER LID <i>HH</i>	\$ 784.00	X
1PC	REAR BUMPER CARRIER <i>HH</i>	\$ 492.00	X
1PC	REAR BUMPER SPONGE <i>HF</i>	\$ 395.00	X
1PC	REAR REINFORCEMENT BAR <i>1st / 2nd</i> 655.20	\$ 1,672.00	✓
1PC	REAR END PANEL <i>ray</i>	\$ 2,495.00	X
1PC	REAR END PANEL TOP GARNISH <i>HH</i>	\$ 385.00	X
1PC	REAR EXHAUST PIPE <i>HH</i>	\$ 1,894.00	X
1PC	REAR EXHAUST MOUNTING <i>HH</i>	\$ 194.00	X

IPC	REAR EXHAUST HEAT SHIELD HH	\$ 255.00	X
8747.40		PARTS SUM:	\$ 31,173.40
7872.66		PARTS LESS 10%:	\$ 3,117.34
		PARTS TOTAL:	\$ 28,056.06

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY TAILGATE WINDSCREEN SEALANT HH	\$ 80.00	40/-
*	TO SUPPLY TAILGATE WINDSCREEN DAMPING SEAL HH	\$ 30.00	X
*	TO SUPPLY TAILGATE INNER TRIM CLIPS HH	\$ 50.00	15/-
*	TO SUPPLY TAILGATE LAMP CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR BUMPER CLIPS HH	\$ 50.00	20/-
*	TO SUPPLY REAR END PANEL SEALANT HH	\$ 80.00	X
*	TO SUPPLY REAR END PANEL TOP GARNISH CLIPS HH	\$ 50.00	X
*	TO SUPPLY REAR NO. PLATE & GARNISH HH	\$ 100.00	45/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00	80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,400.00	600/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,400.00	600/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00	40/-
*	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	\$ 500.00	120/-
*	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	\$ 150.00	60/-
*	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	\$ 120.00	40/-
*	TO RNR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	\$ 200.00	HH
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00	30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00	150/-

LABOUR & S/N TOTAL: \$ 7,360.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 35,416.06

22/07/2021 @ 0930hrs 9712.66
 WA Andrew 4/5 7,500/-
 2/sum 4 days.
 1 nja
 2 kic Andu

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check RA files