



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                 |  |           |
|--|--|-----------------|--|-----------|
| AUTO & GENERAL INSURANCE (S) PL<br>(BUDGET DIRECT INSURANCE)<br>190 CLEMENCEAU AVENUE #03-01<br>SINGAPORE SHOPPING CENTRESINGAPORE<br>239924 |  |                 | Ref: CS/AGI21007832/Kqf3n2<br>Date: 03/08/2021 | Code: AGI |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                 |  |           |
| Insured Veh.   | SLK 9771Z  | Veh. Inspected  | SMP 3807G                                      |           |
| Policy No.   |  | Coverage (\$)   | 0.00   |           |
| Claim No.  | C10010756/HA   | Excess (\$)     | 0.00   |           |
| Assign From  | IVY RATILLA  | Assign Date     | 22/07/2021                                     |           |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                 |  |           |
| Make & Model   | RENAULT SCENIC (A)   | c.c             | 1461   |           |
| Engine No.   | HIDDEN   | Year of Reg.    | 2019   |           |
| Chassis No.  | VF1RFA00063212012  | Colour          | METALLIC BLUE                                  |           |
| Odometer   | 99781 KM   | Steering        | IN ORDER                                       |           |
| Brakes   | IN ORDER   | Modification    | STANDARD ALLOY RIM                             |           |
| General  | GOOD   |                 |  |           |
| <b>3. Conditions of Tyres</b>  |  |                 |  |           |
|  | Size   | Make            | Balance  |           |
| R/H Front Tyre   | 195/55 R20   | GOODYEAR        | 9 mm   |           |
| L/H Front Tyre   | 195/55 R20   | GOODYEAR        | 9 mm   |           |
| R/H Rear Tyre  | 195/55 R20   | TOURADOR        | 8 mm   |           |
| L/H Rear Tyre  | 195/55 R20   | TOURADOR        | 8 mm   |           |
| <b>4. Description of Damages</b>   |  |                 |  |           |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.<br>DAMAGES SEE DETAILS.  |  |                 |  |           |
| <b>5. General Information</b>  |  |                 |  |           |
| Accident Date  | 02/07/2021   | Inspection Date | 26/07/2021                                     |           |
| Survey held at   | MUNICH AUTOCARE PTE LTD<br>60 JALAN LAM HUAT<br>#07-43 CARROS CENTER<br>SINGAPORE 737869 |                 |  |           |
| <b>5a. Remarks</b>   |  |                 |  |           |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.       |  |                 |  |           |
| <b>5b. Estimate Days of Repair</b>   |  |                 |  |           |
| ESTIMATED NORMAL PERIOD FOR REPAIR:  |  |                 | 3 Working Days                                 |           |