

(08/11/13) wef
ASS. REF. BY: Marcus

REF:

CS/MSA21007839/UrF3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD (TP / WS / TP RES / OD RES / EVA / INV / MV)
To Inspect Vehicle No: FBQ6280E
at Workshop m/s Sanfu 10am.
of _____
Insured: SAN367B
Policy No. _____
Claims No. _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S
X	

Bal. or Market Value: \$11k.
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: 181D Vehicle: IN / OUT

Date / Time Action / Instruction LTA \$3400
new bike \$14500
Nett \$7600

Veh No: FBQ6280E Yr Regn: 16/11/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: Honda ADV150ABS 149
Colour: Red A/C: Insured / Std / NI / NA
Sp. Reading: 48063 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: MMHKF6113KK003543
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 110/80-14
R: 130/70-15
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front 7 mm Rear 7 mm
R/Bal. mm R/Bal. mm
L/Bal. mm L/Bal. mm
D.O.A. 20/6/21 D.O.I. 23/7/21
Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear n/s & o/s body
The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

) S + RS. SI

) Photos

) Others

TOTAL



not Affected
here
P/P 3
3 days
the 1st Affected
23/3/21

ASSESSMENT FOR REPAIR : FBQ6280E
HONDA ADV150 ABS CVT
COE EXPIRY : 15 Nov 2029

Lump Sum / Part by Part

Qty	Description	Repairer's Estimate	1st Survey	Repair Survey	Final Survey
1	FRONT TOP RH COWLING <i>cna</i> ✓	64.20	✓		
1	RH FOG LIGHT <i>cna</i> ✓	321.00	✓		
1	MIRROR <i>cut</i> ✓	80.26	✓		
1	RH BRAKE LEVER <i>scr</i> ✓	48.16	✓		
1	BAR END <i>cut</i> ✓	32.10	✓		
1	FRONT FENDER <i>11 X</i>	224.70	X		
1	FORK (SET) <i>11 X</i>	1,284.00	X		
1	RH SIGNAL LIGHT (FRONT) <i>cut</i> ✓	112.36	✓		
1	FRONT BOTTOM RH COWLING <i>cut</i> ✓	385.20	✓		
1	RH FOOTMAT STAY <i>11 X</i>	160.50	X		
1	RH FOOTMAT COVER <i>ground</i> ✓	192.60	✓		
1	PILLION FOOTREST PEG <i>11 X</i>	48.16	X		
1	REAR MUDGUARD <i>11 X</i>	224.70	X		
1	HANDLEBAR <i>11 X</i>	160.50	X		
1	LH TRANSMISSION COVER	288.90	?		
1	LH AIRBOX COVER <i>ground</i> ✓	128.40	✓		
1	EXHAUST MUFFLER COVER <i>cut</i> ✓	256.80	✓		
1	EXHAUST PROTECTOR <i>scr</i> ✓	192.60	✓		
1	EXHAUST CAP <i>cut</i> ✓	96.30	✓		
1	RH REAR COWLING <i>11 X</i>	256.30	X		
1	METAL RACK FOR BOX (HEAVY DUTY) <i>11 X</i>	434.00	X		
		4,991.74			

Special Nett Items

STEERING CONE & BEARING <i>11 X</i>	120.00			
FRONT FORK ALIGNMENT <i>11 X</i>	220.00			
WHEEL ALIGNMENT <i>11 X</i>	120.00			
FRAME ALIGNMENT <i>11 X</i>	200.00			
BOX GIVI <i>cut 300</i>	481.50			

1,141.50

Total Parts

6,133.24

Labour Charges

- 1 Workmanship to renew damage parts & areas

350.00

350.00

Total Parts & Labours Concluded

6,483.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SANFU MOTOR PTE LTD

Company Reg No.: 200612487G

1 Kaki Bukit Ave 6, #02-43, AutoBay@Kaki Bukit, Singapore 417883

Direct Line: 9061 3299 Tel: (65) 6744 7753 Fax: (65) 6744 6010

Email: sanfumotor0243@gmail.com

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	181D
Vehicle Details	
Vehicle No.:	FBQ6280E
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Jul 2021
Vehicle Make:	HONDA
Vehicle Model:	ADV150 ABS CVT
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	KF61E1003554
Chassis No.:	MH1KF6113KK003543
Maximum Power Output:	-
Open Market Value:	\$3,650.00
Original Registration Date:	16 Nov 2019
First Registration Date:	16 Nov 2019
Transfer Count:	1
Actual ARF Paid:	\$548.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	15 Nov 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$4,089.00
COE Rebate Amount:	\$3,400.00
Total Rebate Amount:	\$3,400.00

The information contained herein is correct as at 22 Jul 2021

OK

Motorcycles

Motorcycles for Sale

Class 2B



2020 Honda ADV 150

S\$12,500

 Used

 Meetup

 Jurong West



@sevendiner151020

No ratings yet

Chat

Description

Posted	Make	Type
Yesterday	Honda	Scooter

slightly negotiable
coe November 2030
Mileage 7000km plus
300km plus for 7L petrol (8L Tank)

Rims Sprayed Gold
Pirelli Angel Scooter Tyres

read more

Write a custom message...

Hi, is this still available?

Is the price negotiable?

Can I see more photos?

Sign in to make offer

S\$ 12500

Make Offer

Advertisement

Meet-up



 Jurong West



Meet the seller