



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21007843/Utf3n2 Date: 05/08/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGH 996B	Veh. Inspected	GBB 9702P	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10010976/CD	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	22/07/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN NV200 (M)	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JN1YBAM20U0002994	Colour	SILVER	
Odometer	182923 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R14	TRIANGLE	6 mm	
L/H Front Tyre	185/60 R14	TRIANGLE	6 mm	
R/H Rear Tyre	185/60 R14	FALKEN	6 mm	
L/H Rear Tyre	185/60 R14	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2021	Inspection Date	22/07/2021	
Survey held at	AIM HENG CAR SERVICE PTE LTD 38 WOODLANDS INDUSTRIAL PARK E1 #05-19 SINGAPORE 757700			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	