



# Service Request Details

Claim

S1M03E3G

Reference

CC4/ASM21007854/Apa3 🥒

Loss Date

18 July 2021

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

**Report Date** 

20 Jul 2021 3:05:00 PM

Request Date

22 July 2021

Due Date

22 July 2022

Services

Pre-Repair Survey

#### **Actions**

**Next Step** 

Finish the work







## **Vehicle Information**

Incident Vehicle Registration # SMQ9049H

Make

**TPVD** Honda

Model

Shuttle

### Service Address

, , ,

# Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

#### Claim Handler

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

Messages1

Invoices

History

Documents

Assessment

Metrics

Notes

7/22/2021 VendorEngage



0

0

0

Menu

**TYPE** 

SENT 22/7/21 3:08 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT RE: Re:YOUR REF : S1M03E3G

BODY Noted with thanks.

1

TYPE

SENT 22/7/21 2:46 PM

FROM ANG Yvonne

SUBJECT Re:YOUR REF : S1M03E3G

BODY Detail emailed Hua Meng Spray Painting Workshop

1

TYPE

SENT 22/7/21 12:07 PM

FROM LKK AUTO CONSULTANTS PTE LTD (TP)

SUBJECT YOUR REF: S1M03E3G

BODY Dear Daniel, Please provide workshop details. Than...

1