FAQ English (SG) ▼ Elaine Kuan ▼

Service Requests ••

Claim S1M03E3G

Reference CS3/ASM21007854/Apa3e2

Ø

Loss Date 18 July 2021

Vendor Name LKK AUTO CONSULTANTS

PTE LTD (TP)


Type of Loss Third Party Vehicle Damage

Report Date 20 Jul 2021 3:05:00 PM

Request Date 22 July 2021

Due Date

Services Pre-Repair Survey



Vehicle Information

Incident SMQ9049H

Vehicle

Registration #

Make TPVD Honda

Model Shuttle

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD 383 SIN MING DRIVE, 575717, Singapore 65551188

