



Claim	S1M03E3G
Reference	CS3/ASM21007854/Apa3e2 
Loss Date	18 July 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	20 Jul 2021 3:05:00 PM
Request Date	22 July 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve
invoice

Add Invoice

Vehicle Information

Incident

SMQ9049H

Vehicle
Registration #

Make

TPVD Honda

Model

Shuttle

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

ANG Yvonne

yvonne.ang@axa.com.sg

Additional Instructions

- Messages4
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

▼

▼

+ Upload Documents

Already Attached

NAME		DATE UPLOADED		
NAME	TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2107514.pdf.pdf	Email Sent	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021
 LKKPreRepairInspection.pdf.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	1 November 2021

