

REF: AGI/ 21007886/Kg

Kenneth

5

Veh No: SMT 8906A Yr Regn: 09, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Altis C.C. 1598

Colour in Silver A/C: Insured / Std / NI / NA

Sp. Reading 136118 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: NR0537 EE1.06166646

Gen. Cond: Good / Fair / Poor / Burnt


Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / ~~STD~~ A/Rlm or

Tyre Size: F: 205/55R16

R: _____



Front

R/Bal. 8 mm

L/Bal. 8 mm

D.O.A. 21/7/21

Rear

R/Bal. 8 mm

L/Bal. 8 mm

D.O.I. 23/7/2021

R/Bal.  mm R/Bal.  mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 21/7/21 D.O.I. 23/7/2021

Survey held at

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

Date: Person Contacted: Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction	The O/C / Chassis frame / Body Structure affected due to collision.
1	Crash Error ready	
4/8	112pp 842006 Cohn	(Red \$8607, 67%)

☐: *Prell. Report*

☐ : Final Report

Days Of Repair: 6

Resurvey No. of Trip: 2

Survey Fee:

Transportation

Add Fee: : Site Insp (\$☐ : Interview (\$

☐ Tech Invs (\$

Weekend (\$)

___ S + RS. ___ SI

F. 17. 25

Others

TOTAL

Port Format : TP

Sum / I.B.I. (\$	4200
-----------------------------	------