



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 ATTN: SALIHA SYED YUSOF			Ref: CS3/AIG21006601/Vvf3e2-1 Date: 02/08/2021 Code: AIG	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLW 8814C	Veh. Inspected	GX 7970U	
Policy No.	2070006499	Coverage (\$)	0.00	
Claim No.	2420992591SG	Excess (\$)	0.00	
Assign From	SALIHA SYED YUSOF	Assign Date	23/07/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	NISSAN CABSTAR	c.c	3153	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	JN1SF4F23Z0852735	Colour	SILVER	
Odometer	448833 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	CONDOR	5 mm	
L/H Front Tyre	195 R15C	CONDOR	5 mm	
R/H Rear Tyre	155 R12C	CONDOR	5 mm	
L/H Rear Tyre	155 R12C	CONDOR	5 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	07/06/2021	Inspection Date	11/06/2021	
Survey held at	JEMENTAH MOTOR WORKS BLK 14 DEFU LANE 10 #01-406 SINGAPORE 539195			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		