

(08/11/13) wef

ASS. REC. BY: John

REF:

CC4/FCI21007890/R1a3

966

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLH 281Cat Workshop m/s Volkswagenof 247, Alexandra Rd

Insured:

FCI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

105K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLH 281C

Yr Regn:

2017 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen SHARAN 2.0 TSI c.c 1984

Colour:

BLUE

A/C: Insured / Std / NI / NA

Sp. Reading

80886

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WVN2227N2JV002817

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MID / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/07/21

D.O.I.

27/07/21

Survey held at

Volkswagen

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Repair limit - 38k

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Commercial Vehicles

Quotation

Non binding - Preview

Page

1/2

Company
MS

FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:

Ms.
TAN
LENG LI JULIA
15F LIM TUA TOW ROAD
Singapore 547744

Document no.

Document date

22-07-2021

Customer no.

5211041856

Customer GST-ID

195000106C

Dealer

30001

Job order number

2021027464/ 1

Job order date

22-07-2021

Service Advisor

SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLU281C	7N24MY	20-11-2017	WWWZZZ7NZJV002817	SHARAN HLBMT 162 TSID6F	79,555

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
9801B004	B&P CHECK SHORT CIRCUIT / HARNESS REPAIR	1		5280	#1	280.00	299.60
9801B005	B&P DIAGNOSIS AND PROGRAMMING	1		5480	#1	480.00	513.60
7N0827025H	Rear Trunk Lid repair	1	pcs.	3,059.91	#1	3,059.91	3,274.10
D 169300M2	1k Window Adhesive X	2	pcs.	51.16	#1	102.32	109.48
D 00940104	All Purpose Cleaner X	1	pcs.	97.37	#1	97.37	104.19
D 00920002	Primer X	1	pcs.	28.44	#1	28.44	30.43
D 181802M1	Activator For Precoated W X	1	pcs.	26.15	#1	26.15	27.98
D 00950025	Applicator X	2	pcs.	10.44	#1	20.88	22.34
3CN945087	Additional Brake Light W photo - 3RD BRAKELIGHT	1	pcs.	228.77	#1	228.77	244.78
7P6853630D FOD	Vw Sign Black High Gloss/	1	pcs.	129.48	#1	129.48	138.54
7N0853687 739	Inscription Chrome	1	pcs.	88.80	#1	88.80	95.02
7N0853675F 2ZZ	NAME PLATE - SHARAN	1	pcs.	79.96	#1	79.96	85.56
5K6955711B	Inscription Bright Chrome	1	pcs.	79.96	#1	79.96	85.56
5K6955435	NAME PLATE - 380 TSI	1	pcs.	79.96	#1	79.96	85.56
7N0945308A	Wiper Motor X	1	pcs.	414.82	#1	414.82	443.86
7N0945208	Cap	1	pcs.	8.79	#1	8.79	9.41
7N0945307A	WIPER ARM CAP	1	pcs.	573.26	#1	573.26	613.39
7N0945207	Led Tail Light With Rear	1	pcs.	644.53	#1	644.53	689.65
7N0807417E GRU	RHS TAILLIGHT INNER	1	pcs.	573.26	#1	573.26	613.39
7N0807521C 9B9	Led Tail Light	1	pcs.	644.53	#1	644.53	689.65
7N0807305A	RHS TAILLIGHT OUTER	1	pcs.	573.26	#1	573.26	613.39
7N0807251A	Led Tail Light With Back	1	pcs.	644.53	#1	644.53	689.65
7N0807863	LHS TAILLIGHT INNER	1	pcs.	1,507.35	#1	1,507.35	1,612.86
7N0807375	LHS TAILLIGHT OUTER	1	pcs.	295.10	#1	295.10	315.76
7N0807376	Cover For Bumper Primed	1	pcs.	809.97	#1	809.97	866.67
WHT000931	Spoiler Satin Black	1	pcs.	138.73	#1	138.73	148.44
	Bumper Bracket	1	pcs.	195.09	#1	195.09	208.75
	REINFORCEMENT	1	pcs.	84.26	#1	84.26	90.16
	Foam Insert	1	pcs.	84.26	#1	84.26	90.16
	Attachment Strip	1	pcs.	84.26	#1	84.26	90.16
	BUMPER CTR BRACKET	1	pcs.	84.26	#1	84.26	90.16
	Guide Piece	1	pcs.	84.26	#1	84.26	90.16
	BUMPER SIDE BRACKET LH	1	pcs.	84.26	#1	84.26	90.16
	Guide Piece	1	pcs.	84.26	#1	84.26	90.16
	BUMPER SIDE BRACKET RH	1	pcs.	84.26	#1	84.26	90.16
	Hex Socket Head Collared	4	pcs.	1.23	#1	4.92	5.26
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	SPRAY PAINT	4	pcs.	800.00	#1	3,200.00	3,424.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Company
MS
FIRST CAPITAL INSURANCE LTD
6 RAFFLES QUAY
#21-00
Singapore 048580

Customer Details:
Ms.
TAN
LENG LI JULIA
15F LIM TUA TOW ROAD
Singapore 547744

Page 2/2
Document no.
Document date 22-07-2021
Customer no. 5211041856
Customer GST-ID 195000106C
Dealer 30001
Job order number 2021027464/ 1
Job order date 22-07-2021
Service Advisor SHU SHI TANG

License plate	Model code	First registration	VIN	Model	Mileage
SLU281C	7N24MY	20-11-2017	WVWZZZ7NZJV002817	SHARAN HLBMT 162 TSID6F	79,555

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	MS FIRST CAPITAL DIRECT SETTLEMENT DOA: 19/07/2021 TP VEH: SBS6439E SURVEY BY:						

Quotation valid till 29-07-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	18,230.95	7%	1,329.37	18,990.95	20,320.32
Total	760.00	18,230.95		1,329.37	18,990.95	20,320.32

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90010068
4 days
21/07/21 @ 1040
Resy before paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 20/07/2021 19:55 (SGT)
Date of Accident 19/07/2021 13:40 (SGT)
Exact Location of Accident 756 Upper Serangoon Rd, Singapore 534626
Additional Location Information Upper Serangoon rd
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLU281C

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TAN LENG LI JULIA
NRIC No SXXXX966G
Email Address juliatanll@hotmail.com
Mobile Phone No (Phone) +65-96952084
Alternative Phone No +65-96952084

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Sharan
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Private car
Transmission Auto
CC 1984

INSURANCE COMPANY

Name of Insurance Company Aviva Ltd
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 10881659
Cover Note Number NA

DRIVER

Name of Driver TAN LENG LI JULIA
NRIC No SXXXX966G

Birth	12/05/1975
Location	Outdoor
Of Driving Pass	19/09/1997
ing experience	23 YEARS AND 10 MONTHS
der	Female
obile Number	(Phone) +65-96952084
Phone Number	+65-96952084
mail Address	juliatanll@hotmail.com
Address	15F Lim Tua Tow rd
Address complement	Unit 15F
Postcode	547744
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	Teo Chye hong
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

My vehicle SLU281C was stationary along upper Serangoon road while waiting for the traffic turn into green .While my vehicle was stationary, suddenly I felt an slight impact coming from my rear bumper and discover that the 3rd party SBS6439E had collided onto my rear bumper. I managed to take some photos and exchange particulars with the 3rd party. No injuries was involved at the scene.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBS6439E
Vehicle Manufacturer	Mercedes
Vehicle Model	Citaro
Vehicle Variant	-

Colour	Green
Category	Bus
Name of Driver	Fong Kin Kuan
Contact Number	-
Address	Na
Address complement	Na
Postcode	Na
Insurance Company Name	-
Nature Of Damage	Na
Details of property damaged in accident	Na
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

GIA/MC SketchPlanForm_V3

ACCIDENT DIAGRAM

Ver 30042021

UPP
PAYA LEBOR
RD

A SLU 281C BOUNDARY RD
B SBS 6439E

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
MUHAMMAD SUMARDI BIN MOHD AFFANDI
Reporting Centre Personnel's Signature
Name:
NRIC/IRN No.:

SKETCH PLAN

REFER TO ATTACHED ACCIDENT DIAGRAM

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

My vehicle SLU281C was stationary along upper Serangoon road while waiting for the traffic turn into green. While my vehicle was stationary, suddenly I felt an slight impact coming from my rear bumper and discover that the 3rd party SBS6439E had collided onto my rear bumper. I managed to take some photos and exchange particulars with the 3rd party. No injuries was involved at the scene.

DECLARATION

(We declare the foregoing particulars are true in every respect)

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

VERIFY BY AJAX MARS (ARC)
REPORTING OFFICER

MUHAMMAD SUMARDI BIN MOHD AFFANDI

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	966G
Vehicle No.:	SLU281C
Vehicle to be Exported:	No
Intended Deregistration Date:	28 Jul 2021
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	SHARAN 2.0 TSI 7N24MY
Primary Colour:	Black
Manufacturing Year:	2017
Engine No.:	DED015088
Chassis No.:	WVWZZZ7NZJV002817
Maximum Power Output:	162.0 kW (217 bhp)
Open Market Value:	\$34,839.00
Original Registration Date:	20 Nov 2017
First Registration Date:	20 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$40,775.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	19 Nov 2027
PARF Rebate Amount:	\$30,581.00
COE Expiry Date:	19 Nov 2027
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,414.00
COE Rebate Amount:	\$36,233.00
Total Rebate Amount:	\$66,814.00

The information contained herein is correct as at 28 Jul 2021

OK

Volkswagen Sharan 2.0A TSI

[Overview](#)[Financial](#)[Accessories](#)[Similar](#)[Research](#)[Photos](#)[Map](#)

OSCARS

AUTO PRIVATE LIMITED

Price**\$96,800****Depreciation** ?

\$13,530 /yr

[View models with similar depre](#)**Reg Date**

22-Mar-2017

(5yrs 7mths 21days COE left)

Mileage

57,000 km (13.1k /yr)

Manufactured ?

2017

Road Tax ?

\$1,194 /yr

Transmission

Auto

Dereg Value ?

\$60,557 as of today (change)

OMV ?

\$34,815

COE ?

\$53,106

ARF ?

\$40,741

Engine Cap

1,984 cc

Power

162.0 kW (217 bhp)

Curb Weight ?

1,790 kg

No. of Owners ?

1