

Hsiang Zang

Veh No: SJR 4519L Yr Regn: 13/5/2009

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Zenith Vios C.C. 1494

Colour white A/C: Insured / Std / NI / NA

Sp. Reading **NO BATTERY** T/Radio: Insured / Std / NI / NA

Eng/No: 15Z X905940

C/No: MR053H4930512445

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55/15

R: 195/55/15

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *Hankook*

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 10/7/2021 D.O.I. 26/7/2021

Survey held at Bithost

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range 4,000/r - 5,000/r
	Recommended CER is LS \$ 4300.00
	MV 17,000/r
	PV 6,943/r
	NV 10,057/r

Total in
3/9/2021

☐: Prelim. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

$$S + RS \rightarrow S$$

Photos

) officers

Per ~~in~~ Format:

LEADERSHIP TRAINING / I.E.I. (C)

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$

Tech. Invs (\$)

☐ Weekend (\$)

TOTAL