



Your Ref : 5756318416SG

Date: 30th July 2021

Our Ref : CS/AIG21007936/Evf3e2

M/s AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way #09-16

AIG Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMK 4708D
ACCIDENT ON 11/07/2021**

Instruction was received to inspect the vehicle Reg. No. SMK 4708D. The inspection was conducted on 11/07/2021 at the premises of M/s Cycle & Carriage Automotive Pte Ltd (Pandan Gardens), 209 Pandan Gardens, Singapore 609339.

The following vehicle information was recorded:


Registration Number	: SMK 4708D
Make/Model	: Kia Cerato 1.6 (A) EX
Year of Registration	: 2019
Body Colour	: Grey
Chassis Number	: KNAF3416MK5036904
Engine Capacity	: 1591 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 82,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 31,047.00)
Nett Liability	<u>S\$ 50,953.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.