

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

China (H8) Jy

Date: 23.07.2021

Time: 13:40:44

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305479640
 REGN NO : SHC7213X
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 14.07.2016
 DATE/TIME IN : 23.07.2021 10:15
 ACCIDENT DATE : 22.07.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	COVER ASSY-RR BUMPER#	1	1,106.00	20.00	884.80	de -	
0002 04-01-0103-0738-G	COVER-RR BUMPER LWR#	1	228.00	20.00	182.40	R	
0003 04-01-0103-0739-G	ABSORBER-RR BUMPER ENERGY	1	119.50	20.00	95.60	R un	1128
0004 04-01-0103-0740-G	BEAM-RR BUMPER#	1	428.40	20.00	342.72	R un	902.40
0005 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	un	SN 50
0006 04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00	un	952.40

SUB-TOTAL : 1,573.12

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 20-05	ADVERTISMENT STICKER-BUMPER	50.00	un
0003 20-05	ADVERTISMENT STICKER-FENDER	200.00	un 810
0004 L	REMOVE/REFIX REVERSE SENSOR	80.00	30

952.40
 810
 1762.40
 1/58/1400
 02 days #

Tanjiu 97495779
 WP 23/7/21 2:50pm
 02 days
 1/58/1400 after repair
 tanjiu@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: