

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : YN 7104T
Vehicle Model : MIT. CANTER
Accident Date : 23.07.2021
Original Reg Date : 18.12.2014

Date : 27.07.2021
Chassis : FEB21EA01051
TP Ins. **AIG**

ESTIMATE

1	1 pc	Rear Number Plate Lamp			92.00	L
2	2 pcs	Taillamp Assy	293.00		586.00	L
3	1 pc	Taillamp Assy Base LH			152.00	L
4	1 pc	Spare Tyre Carrier			352.00	L
					1,182.00	
					Less 25%	295.50
					886.50	886.50

Special Nett

1	2 pcs	Tailgate Door Assy "Fiber"	RH X NN	1,800.00	LH- 3,600.00	1800
2	2 pcs	Tailgate Door Hinges Bottom (Stainless)	RH X NN	180.00	LH-bt 360.00	180
3	2 pcs	Tailgate Door Opener Bar (Stainless)		500.00	bt 1,000.00	900
4	2 pcs	Tailgate Door Opener Bar Hinge (Stainless)		150.00	X NN 300.00	
5	2 pcs	Tailgate Door Opener Bar Catch	RH X NN	150.00	LH-bt 300.00	150
6	1 pc	Tailgate Door Safe Lock Bar LH			bt 320.00	
7	1 pc	Rear Step Cross Member			bt 380.00	
8	4 pcs	Rear Protector Big Stopper		150.00	bt 600.00	
9	1 pc	Rear Number Plate			X NN 30.00	
10	1 pc	Rear Bumper			bt 1,000.00	
11	2 pcs	Rear Bumper Bracket		250.00	bt 500.00	
12	1 pc	Rear Tyre			X NN 380.00	
13	2 pcs	Rear Door Sticker with Company Logo		500.00	800 1,000.00	
14	1 pc	60km Sticker			bt 15.00	
15	1 pc	Rear Refrigerator Surround Frame (Stainless)			bt 1,800.00	1400

7845

Labour charge

LKK Auto Consultants hence notify the Repairer of the following:

Panel Beating	• To resurvey before/after spray painting	800 1,200.00
Spray painting	• To display damaged part(s) during resurvey • Parts prices are subject to confirmation	800 1,000.00
Anti rust	• Third party survey is on a "Without Prejudice" basis	30 60.00
Check Wiring	• No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company	30 40.00

1660

14,771.50
Less 20% 2,954.30
Lump sum 11,817.20

10391.50

LS\$8300

7 DAYS

Tanpin 17/7/21
28/7/21
c/s Resurvey After
7 days
tanpin@lkhauto.com