



Your Ref: 20/21/21/VC05/024730

Date: 06th March 2023

Our Ref: CS1/LPC21008002/Tvy3m4

M/s Lonpac Insurance Bhd

300 Beach Road

#17-04/07 The Concourse

Singapore 199555

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SG 5320G

INSURED VEHICLE: YN 8362H

ACCIDENT DATE: 26/06/2021

We thank you for your instruction on 28/07/2021.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SG 5320G from M/s SBS Transit Ltd.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SG 5320G
Make & Model	: Volvo B9TL Eu5 DD AC 3 Axle
Chassis Number	: YV3S4P923GA176475
Year of Registration	: 2016
Engine Capacity	: -

- 2. We recommend that the repairs of the entire damage require about 1 (One) working day to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.