

REF: CS1/LPC21008002/Tvy3

Special Instruction:

ASSIGNMENT (Office)

From (Person): ONG LI LI of LONPAC Date/Time: 28/07/2021

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

Third Parties:

Claimant:

Surveyor:

Workshop: SBS TRANSIT LTD (HQ)

### OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SG 5320G Insured: YN 8362H

at Workshop m/s **SBS TRANSIT LTD (HQ)**

of Hougang Depot 4, Defu Avenue 1

Policy No: \_\_\_\_\_ Claim No: 20/21/21/VC05/024730

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_  
(Client's Record) \_\_\_\_\_ D.O.A. 26/06/2021

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 3/3/23 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_\_ days (Red \$ \_\_\_\_\_ / \_\_\_\_\_ %; Original \_\_\_\_\_ days)

Date/Time: 3/3/23 Submit Final Fig \$4066, 1 days (Red \$ 1636.60/ 28%; Original      days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)**

<b>Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)</b>	
---	--

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_