

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

I was doing Svc 87 in SG5320G on the mentioned date and time. My direction is towards Bedok Bus Interchange. At around 1215hrs, I was travelling along Eunos Link. While I was proceeding from a slip road between Eunos Lk & Kaki Bukit Ave 1, I suddenly felt a jerk from the back. I immediately went down to take a look and discovered the lorry driver hit onto our bus rear. 25Pax onboard. No injury. I reported to OCC. After exchanging particulars, I was told to resume service. That's all.

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... No  
 Was there any video captured by Car Camera? ..... No  
 Was there any audio recorded? ..... No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... YN8362H  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Goods vehicle  
 Name of Driver ..... Wilson Ng  
 Contact Number ..... (Phone) +65-94352282  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... HEAD TO REAR  
 Details of property damaged in accident ..... Front left panel scratched  
 No. Of Passenger (Including Driver) ..... -

#### PASSENGER 1

Name ..... UNKNOWN  
 Gender ..... Female