

ASS. REC. BY:

CS3/ TU 21005232/Gvf3-1

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

SJR 9548P

Policy No.

D21MPC0000770

Claims No.

MPC2021D0001939


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A. 25/4/21

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C Chassis frame / Body Structure affected due to collision.

Rear

R/Bal.

L/Bal.

D.O.A.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2) 5/8/21-Typist

Report Formed: TP

Emp. Sign / Date:

Days Of Repair: 6

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Misc. Insp (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Other:

TOTAL