

|   |   |          |   |   |   |   |        |   |   |             |
|---|---|----------|---|---|---|---|--------|---|---|-------------|
| ⏪ | < | 1 of 2 ? | > | ⏩ | ↺ | ↻ | 100% ▼ | 🖨 | 📄 | Find   Next |
|---|---|----------|---|---|---|---|--------|---|---|-------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                      |                                                                                                           |                          |            |  |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------|--------------------------|------------|--|
| SMRT AUTOMOTIVE SERVICES PTE LTD                                                                                                       |                                                                                                           | Ref: CS/SMR21008049/Guf3 |            |  |
| 60 WOODLANDS INDUSTRIAL PARK                                                                                                           |                                                                                                           | Date: 29/07/2021         |            |  |
| E4SINGAPORE 757705                                                                                                                     |                                                                                                           | Code: SMR                |            |  |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                      |                                                                                                           |                          |            |  |
| Insured Veh.                                                                                                                           | SG 1880H                                                                                                  | Veh. Inspected           | SLG 598M   |  |
| Policy No.                                                                                                                             |                                                                                                           | Coverage (\$)            | 0.00       |  |
| Claim No.                                                                                                                              | BUS/07/21/5036                                                                                            | Excess (\$)              | 0.00       |  |
| Assign From                                                                                                                            | HUA YEN                                                                                                   | Assign Date              | 29/07/2021 |  |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                          |                                                                                                           |                          |            |  |
| Make & Model                                                                                                                           |                                                                                                           | c.c                      | 0          |  |
| Engine No.                                                                                                                             | HIDDEN                                                                                                    | Year of Reg.             |            |  |
| Chassis No.                                                                                                                            |                                                                                                           | Colour                   |            |  |
| Odometer                                                                                                                               | -                                                                                                         | Steering                 |            |  |
| Brakes                                                                                                                                 |                                                                                                           | Modification             |            |  |
| General                                                                                                                                |                                                                                                           |                          |            |  |
| <b>3. Conditions of Tyres</b>                                                                                                          |                                                                                                           |                          |            |  |
|                                                                                                                                        | Size                                                                                                      | Make                     | Balance    |  |
| R/H Front Tyre                                                                                                                         |                                                                                                           |                          | mm         |  |
| L/H Front Tyre                                                                                                                         |                                                                                                           |                          | mm         |  |
| R/H Rear Tyre                                                                                                                          |                                                                                                           |                          | mm         |  |
| L/H Rear Tyre                                                                                                                          |                                                                                                           |                          | mm         |  |
| <b>4. Description of Damages</b>                                                                                                       |                                                                                                           |                          |            |  |
|                                                                                                                                        |                                                                                                           |                          |            |  |
| <b>5. General Information</b>                                                                                                          |                                                                                                           |                          |            |  |
| Accident Date                                                                                                                          | 27/07/2021                                                                                                | Inspection Date          | 30/07/2021 |  |
| Survey held at                                                                                                                         | RICO 60 AUTO SERVICES PTE LTD<br>8 KAKI BUKIT AVENUE 4<br>#02-24 PREMIER @ KAKI BUKIT<br>SINGAPORE 415875 |                          |            |  |
| <b>5a. Remarks</b>                                                                                                                     |                                                                                                           |                          |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                                           |                          |            |  |