

(08/11/13) wef

ASS. REC. BY: ASU

REF:

CS3/ASM21008062/RINC

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: JTR 355

at Workshop m/s PROJECT 8 MOTORWORKS

of 61, WOODLANDS Ld PK E9, 09 PREMIER #01-03

Insured: ASM SHC 3248Y

Policy No.

Claims No. S1M03EKN


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GIA / PR Seen: Consistent?: Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No:

JTR 355

Yr Regn: /

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA

C.C.

Colour:

MULTI

A/C: Insured / Std / NI / NA

Sp. Reading

36685

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / Rim / STD A/Rim or

Tyre Size:

F:

70/90-17

R:

80/90-17

BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

19/01/21

D.O.I.

29/07/21

Survey held at

PROJECT 8 MOTORWORKS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

ESTIMATE RANGE OF REPAIR - (3K-4K) / 4 days

repairer did not provide us GIA report

4/10/2021 Submit PRS.

Date/Time, File Pass to?

☐

Prel. Report

1) 4/10 TYPIST

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

) S + RS, SI

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format: SMART CLAIM - PRS

Lump Sum / I.B.I: (\$)

TOTAL