

305480389 Our Job Ref No ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969 Fax: 6546 8156 02/08/21 Date **FINALIZATION FORM** LKK Fax: **TAUFIKH** Attn : SHC7300C DOA: 28.07.21 The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-SLL3308M 1. The repair job shall bill to: AIG 2. The finalized amount shall be: Spare Parts after List discount (a) ### (b) Labour Charges **Total for Part-By-Part Repair Cost** ΓNI (c.) Lumpsum Repair (if applicable) Total for Lumpsum repair cost after Less: 20% \$2,400.00 Final Lumpsum Repair cost 3. Estimated normal period for repairs: 3 working days 4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days 5. Thank you for your assistance. We confirm the estimates and finalized amount Signature : Signature: Taufikk JUMANI Name Name 16/8/21 Tel 6214 8315 Date : 65468156 Fax For Official Use Only Document Confirm By Attached Remarks Item Amount (Signature) Yes or No YES 1. Rental Rate P/Day Loss of Income Paid 3. Survey Fees 4. LTA Search Fee \$7.49 5. Medical Fees (on behalf of driver, if applicable) Overrun

Remarks: