

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	AXA INSURANCE	PTE LTD		Ref:	CC4/ASM21008075/Apa3q2	
	8 SHENTON WAY AXA TOWERSING			Date:	26/07/2022	
	ATTN:KHOR SAW	THENG		Code:	ASM	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	YP 7946U	Veh. Inspected		GBJ 6847H	
	Policy No.	P1847906	Coverage (\$)		0.00	
	Claim No.	S1M03EL3	Excess (\$)		0.00	
	Assign From		Assign Date		09/07/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	NISSAN NV200	c.c		1461	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	VSKYBAM20Z0179058	Colour		WHITE	
	Odometer	69579 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	175/70 R14	YOKOHAMA		6 mm	
	L/H Front Tyre	175/70 R14	YOKOHAMA		6 mm	
	R/H Rear Tyre	175/70 R14	YOKOHAMA		6 mm	
	L/H Rear Tyre	175/70 R14	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	28/07/2021	Inspection Dat	е	30/07/2021	
	Survey held at	MG SOLUTION PTE LTD	•			
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					