

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/NG XUE LI, SHERLENE (HUANG XUEL		
Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Reg No/Reg Date	SMR4117Y / 03/01/202		
	Date In/Mileage	/ 48709		
	Chassis No	KNAF3416ML5059975		
	Engine No	G4FGKH739336		
	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	29/07/2021/ 16:57	BLE	261 / Edwin Caina		37006		
		Description of Goods	s / Service	S	Qty	Unit Price	Disc%	Amount
E PNT88000	2111252	DD 5110 8411 - 500-511						2400.00
		, RR END PNL , BOOTL: _ , LHR FENDER & RHR		LID SPOILER				
E PNT98000	N FLK FINL	. , LIK FENDER & KRK	FENDER					2100.00
	RR BUMPER	R , RR END PNL , BOOT	TLID , BOO	OTLID SPOILER .				2100.00
LHR FEND			•	•				
E PNT88000								120.00
	REFIT BO	OTLID COMPONENT						100.00
E PNT88000	DEETT DE	R FLR BOARD , CARPET	9. TOTM					120.00
A E/1000000				m				30.00
CHECK WI	RING ELEC	CTRICAL SYSTEM	247					Q 1.00
A 10028901			511			7.7		120.00
TO CARRY	OUT DIAG	SNOSTIC CHECK ON ELEC	TRONIC GO	ONTROL SYSTEM	66	フ		50.00
FI SQUDICT		PLATE WITH CASING						50.00
E PNT88000	NOPIDER	FEATE WITH CASING						80.00
	REFIT RE	VERSE SENSOR						55155
M SUNDRY								220.00
SUPPLY RI	EVERSE SE	INSOR					- 1	
M SUNDRY	ri connoc	ION ON AFFECTED AREA						40.00
M SUNDRY	II CURRUS	ITON ON AFFECTED AREA	13					60.00
SUPPLY BO	DDY PNL S	EALANT						33.02
M SUNDRY								40.00
SUPPLY C	RC BADGE							00.00
M SUNDRY Sundries								20.00
M K3 BOOT I	TP SPOTE	FR			1.00	211.00	00.00	211.00
M PANEL ASS					1.00	1297.00		1037.60
M HINGE ASS					1.00		20.00	77.60
M HINGE ASS					1.00		20.00	77.60
M W/STRIP-	TRUNK LID	OPNG			1.00	100.00	20.00	80.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Co Reg No : 199405410K

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

KIV

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info			
AIG Asia Pacific Insurance Pte.	Cust No/Name	/NG XUE LI, SHERLENE (HUANG XUEL		
Ltd.	Reg No/Reg Date	SMR4117Y / 03/01/202		
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 48709		
78 SHENTON WAY #09-16	Chassis No	KNAF3416ML5059975		
AIG BUILDING SINGAPORE 079120	Engine No	G4FGKH739336		
Contact No 64191000	Make/Model	KIA/CERATO 1.6 A EX G333		
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK		

Account No	Terms	Date/Time Printed	CSE	Operator	232.435	WIP No		
LAX00000	Credit	29/07/2021/ 16:57	BLE	261 / Edwin Caina		37006		
		Description of Good	s / Services		Qty	Unit Price	Disc%	Amount
M TRIM ASS					1.00	202.00		161.60
M LATCH AS					1.00	112.00		89.60
M STRIKER					1.00		20.00	32.00
M LOGO ASS		В			1.00		20.00	25.60
M EMBLEM-C					1.00		20.00	22.40
M LAMP ASS					1.00	690.00		552.00
		OMB INSIDE,LH			1.00	608.00		486.40
		OMB INSIDE,RH			1.00	608.00		486.40
		OMB OUTSIDE,LH			1.00	675.00		540.00
		OMB OUTSIDE, RH			1.00	675.00		540.00
M PANEL AS			п 🗆	ma	1.00		20.00	259.20
M TRIM ASS		NSVERSE L	\bigcirc 5 \vdash 1		1.00		20.00	32.80
M MAT ASSY		COVERING			1.00	211.00		168.80
M COVER-RR					(4.b)	651.00		520.80
M COVER-RR		LWR			1.00	241.00		192.80
M COVER-RR					1.00		20.00	15.20
M COVER-RR					1.00		20.00	15.20
M LAMP ASS					1.00	181.00		144.80
M LAMP ASS					1.00	181.00		144.80
M EXTN WIR		-BWS			1.00	207.00		165.60
M BEAM-RR					1.00	318.00		254.40
M STAY-RR					1.00		20.00	52.00
M STAY-RR					1.00		20.00	52.00
M BRACKET-I					1.00		20.00	7.20
M BRACKET-I					1.00		20.00	7.20
M BRACKET-I					1.00		20.00	4.80
P BRACKET-I					2.00		20.00	9.60
M ANTENNA					1.00		20.00	36.80
M COVER-RR					1.00		20.00	26.40
		BPR SIDE UPR,L			1.00		20.00	20.00
M COVER-RR	BUMPER L	JNDER,LH			1.00	33.00	20.00	26.40
		SURVEYOR NA	ME:					
Confirm & a	ccepted b							
		DATE:		7	% GST on	Net 11976.6		11,976.60 838.36
		REMARKS:				tal Payabl		12,814.96
Authorized	signatorv	and company stamp				-		
	<u> </u>							

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

- policy liability.
 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information

Country/State of Loss

29/07/2021 16:54 (SGT) 29/07/2021 10:25 (SGT)

Singapore

JUNCTION OF CANBERRA ROAD & CANBERRA LINK

Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number

SMR4117Y

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

Email Address Mobile Phone No

Alternative Phone No

No

NG XUE LI, SHERLENE

SXXXX543D

ENELREHS07@GMAIL.COM

(Phone) +65-97937906 (Home) +65-97937906

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle?

Vehicle Category Transmission

CC

Kia

Cerato

Private use

Yes

Private car

Auto

1600

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

Policy Number Cover Note Number AIG Asia Pacific Insurance Pte. Ltd.

Comprehensive

No


2000000418

DRIVER

Name of Driver

NRIC No

NG XUE LI, SHERLENE SXXXX543D



Date Of Birth Occupation

Date Of Driving Pass

Driving-experience

Gender

Mobile Number Alt, Phone Number

Email Address Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

Number of vehicles involved in the accident

Was anybody injured in the Accident?

Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged?

Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

soliciting/oriening accident claims as

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Was notice of intended Prosecution given?

If yes, against whom?

CIRCUMSTANCES OF ACCIDENT

REFER ATTACHMENTS.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Was there any audio recorded?

Yes

03/09/1987

18/04/2007

#06-1451

760791

Yes

No

Clear

Dry

No

Yes

No

Yes

1

No

No

No

2

14 YEARS AND 3 MONTHS

ENELREHS07@GMAIL.COM

(Phone) +65-97937906

(Home) +65-97937906

BLK 791 YISHUN AVE 2

Collision - Head to Rear

Indoor

Yes

No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

Vehicle Manufacturer

Vehicle Model Vehicle Variant

Vehicle Colour

Vehicle Category

Name of Driver

Contact Number

Address

Address complement

YP4544R

isuzu

White

Commercial vehicle

ZHANG MING FEI

(Phone) +65-92726784

-

-

(f) Accident report SC1A217T0002

Page 2 of 29

Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

INJURED PERSONS DETAILS

INJURED 1

Name of injured person NG XUE LI, SHERLENE

Address

Address Complement -

Post Code - Approximate Age Years Old -

Injuries Sustained NECK & BACKACHE FROM WHIPLASH

Injured person in which vehicle? SMR4117Y

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Mu 29/7/21		EM
Policyholder's Signature / Date &	Driver's Signature (If driver is not the policyholder) / Date	Witnessed by Reporting Centre
Time	& Time	Personnel
Skotch Plan		

٢

Icar

Describe Circumstances of the Accident
I was driving along Canberra Road and turning left anto camberra
Link at around 10.20-1025am on 29/7/2021. Istopped at the
proken white line after the zebra crossing to check my blind
cost for any vehicles. Before I turned out, I telt an limpact
from behind and my car, surged forward beyond the
broken white line sold stopped my car and s Lovry
driver stopped his vehicle to provide his details. sastained
/ Sustained necleache and badeache from the incident - Have usital
a clinic and was given 2 days MC.
when I came out it the vehicle I hoticed that it was
a white I suzu lovey that hit into the rear of my
car (SMR41177)

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date

Witnessed by Reporting Centre Personnel



CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

: NG XUE LI, SHERLENE (HUANG XUELI) Name of Policyholder

Period of Insurance : 03 Jan 2020 To 02 Jan 2022

Engine No. G4FGKH739336

Chassis No. : KNAF3416ML5059975 Vehicle No. **SMR4117Y** Policy No. 2000000418

Endorsement No.

Issued Date 09 Jan 2020

ABOUT THE COVER

Make/Model : KIA Cerato

Engine Capacity/Tonnage: 1,591.00 CC Sum Insured : Market Value First Year of Registration : 2020 **Driver Restriction** Off Peak Car: No Insuring with COE/PARF : Yes : NA

Person or Classes of Persons Entitled to Drive*:

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

NG XUE LI, SHERLENE (HUANG XUELI) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1.Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

2.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000 3.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800 4.Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles(Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Metaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504622235

C&CKICP2 - KHENG

239 ALEXANDRA ROAD SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.

This computer generated document does not require a signature.

SSCASE