SS. REC. BY: TOUM	REF: (.53/11) 2160	16746/B+f3-1	Denise
TO AND		SIGNMENT	
From:		Veh No: SJH 9273J Type: M.Carl M.Cycle / Bus / Van / Lor	Yr Regn: 38/8/2008 rry /.Taxi / Prime Mover /
on PIWS/TP RES/OD RES/EVA/INV/MV To Inspect Vehicle No: SJH 9273J at Workshop m/s Assure Auto Assist of IH Amk St 63 BUK B Insured:		Make: Honda Airwage Colour Silver Sp.Reading 194469 Eng/No: L15A5159145	A/C: Insured / Std / NI / NA T/Radio: Insured / Std / NI / NA
Policy No. Claims No. Sum Insured: (Client's Record)		C/No: CJ1207737 Gen. Cond: Good / Fail / Poor / Burnt Steering: Inorder / Jammed / Leaked / Brake: Inorder / Jammed / Leaked /	Burnt or
(Policy Condition) Remark: The veh had commen repair at the time of i	ced its	Modi: MID / S/Rim / STD A/Rim or Tyre Size: F: 185/65/ R: 185/65/ //S BS / DUN / EXNOVA / GY / FS / LIZA TOYO / YOKO or	14 MIC 14 NEUTON
Lum Sum: CA / REV / REP. / 24	Consistent?: Yes or No Consistent?: Yes or No days Res.: Yes or No 3 Val.: Yes or No	Front R/Bal. 5 mm L/Bal. 5 mm D.O.A. 16/66/2021 Survey held at ASSWE Des. of Damages: Frt / Real? O/S OUT The U/C / Chassis frame / Box	Auto Assist
	photos taken en	16/6/2021 15:02:52 PM 12/6/2021 15:27:46 PM	
MV 164 PV 74 NV 9,5	red: 2400;35 lump sum \$44	100, 6days	Buin >1/6/20
Date/Time, File Pass to? 1) Date/Time, File Return to? 2)]: Preli. Report]: Final Report Ad	Days Of Repair: Resurvey No. of Trip: d Fee: Site Insp (\$	Survey Fee: Transportation:)s + Rssi) Photos
Reputormak: Lump Sum/I.E.I: (%)	: Tech. Invs (\$) Officers

TOTAL