

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: AIG	DATE	: 29-Jul-21
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SKC9072L		
MODEL	: CHEVROLET CRUZE 1.6		Cecilin
CHASSIS NO			
ACCIDENT DETAILS		DATE	: 28-Jul-21
		TIME	: 15:15HRS
THIRD PARTY REQUESTOR / CONTACT		:	JACK LI

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>Repld</i>	1	\$ 1,120.20	\$ 1,120.20
2	FRONT BUMPER SIDE RETAINER RH <i>nc</i>	1	\$ 72.50	\$ 72.50
3	FRONT FENDER RH <i>Dented</i>	1	\$ 650.30	\$ 650.30
4	FRONT FENDER SIGNAL LAMP LH <i>2</i>	1	\$ 60.20	\$ 60.20
5	FRONT FENDER INNER COWLING LH <i>1 x 1</i>	1	\$ 170.20	\$ 170.20
6	HEADLAMP RH <i>1 x 1</i>	1	\$ 1,355.20	\$ 1,355.20

TOTAL PRICE \$ 3,428.60

LESS 10% \$ 342.86

SUB TOTAL PRICE \$ 3,085.74

1846
1661.40

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
2	FRONT BUMPER LOWER LID <i>Regis</i>	1	\$ 1,200.00	\$ 1,200.00
3	FRONT FENDER INNER COWLING CLIPS(SET) <i>mp</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ 1,240.00

20

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,000.00	400	
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,000.00	600	
3	TUFF COAT	\$ 250.00	30	
4	WIRING CHECK	\$ 120.00	30	

TOTAL

\$2,370.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 4,325.74
 TOTAL LABOUR COST : \$ 2,370.00
 TOTAL REPAIR COST : \$ 6,695.74

APPROVED DETAILS

SURVEYOR :

CONTACT NO :

FAX :

PART BY PART / LUMP SUM :

NO OF DAYS

:

Adnan Lj
 H/S 30/07/21
 04 Days.

Nett Value : 1.2K
 H.S.

total: 2741.40

H/S: 1.2K
 (Nett Value).

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: